



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 17.DEC.2022 09:35:36

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 17.DEC.2022 09:35:54

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 17.DEC.2022 09:36:13


Band 2_1.4 MHz_Middle_16QAM_RB6#0



Date: 17.DEC.2022 09:36:31




Date: 17.DEC.2022 09:36:47




Date: 17.DEC.2022 09:37:04

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 17.DEC.2022 09:37:21

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 17.DEC.2022 09:37:36

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 17.DEC.2022 09:37:52

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 17.DEC.2022 09:38:07

Band 2_3 MHz_High_QPSK_RB15#0




Date: 17.DEC.2022 09:38:23

Band 2_3 MHz_High_16QAM_RB15#0




Date: 17.DEC.2022 09:38:38

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 09:38:55

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 09:39:13

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 17.DEC.2022 09:39:30

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 17.DEC.2022 09:39:47

Band 2_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 09:40:06

Band 2_5 MHz_High_16QAM_RB25#0




Date: 17.DEC.2022 09:40:28

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 17.DEC.2022 09:40:46

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 17.DEC.2022 09:41:05

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 17.DEC.2022 09:41:25

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 17.DEC.2022 09:41:44

Band 2_10 MHz_High_QPSK_RB50#0




Date: 17.DEC.2022 09:42:04

Band 2_10 MHz_High_16QAM_RB50#0




Date: 17.DEC.2022 09:42:24

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 17.DEC.2022 09:42:48

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 17.DEC.2022 09:47:54

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 17.DEC.2022 09:48:14

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 17.DEC.2022 09:48:36

Band 2_15 MHz_High_QPSK_RB75#0




Date: 17.DEC.2022 09:48:58

Band 2_15 MHz_High_16QAM_RB75#0




Date: 17.DEC.2022 09:49:20

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 17.DEC.2022 09:49:44

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 17.DEC.2022 09:50:04

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 17.DEC.2022 09:50:27

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 17.DEC.2022 09:50:50

Band 2_20 MHz_High_QPSK_RB100#0



Date: 17.DEC.2022 09:51:09

Band 2_20 MHz_High_16QAM_RB100#0



Date: 17.DEC.2022 09:51:32

* RBW 30 kHz Delta 1 [T1]
 * VBW 100 kHz -0.64 dB
 * Att 25 dB
 SWT 15 ms 1.266000000 MHz

Ref 30 dBm Offset 11 dB
 30 Offset 11 dB
 20
 10
 0
 -10
 -20
 -30
 -40
 -50
 -60
 -70

D1 15.17 dBm
 D2 -10.83 dBm
 T1
 T2
 T
 T

OBW 1.104000000 MHz
 Marker 1 [T1]
 -10.43 dBm
 1.710070000 GHz
 Temp 1 [T1 OBW]
 -1.12 dBm
 1.710148000 GHz
 Temp 2 [T1 OBW]
 -1.37 dBm
 1.711252000 GHz

1 PK
 MAXH


LVL
 3DB

Center 1.7107 GHz
 300 kHz/
 Span 3 MHz

Band 4_1.4 MHz_Low_16QAM_RB6#0




Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 17.DEC.2022 09:52:23

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 17.DEC.2022 09:52:41

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 17.DEC.2022 09:52:56

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 17.DEC.2022 09:53:14

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 17.DEC.2022 09:53:31

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 17.DEC.2022 09:53:46

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 17.DEC.2022 09:54:02

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 17.DEC.2022 09:54:20

Band 4_3 MHz_High_QPSK_RB15#0




Date: 17.DEC.2022 09:54:35

Band 4_3 MHz_High_16QAM_RB15#0




Date: 17.DEC.2022 09:54:54

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 09:55:14

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 09:55:33

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 17.DEC.2022 09:55:49

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 17.DEC.2022 09:56:11

Band 4_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 09:56:28

Band 4_5 MHz_High_16QAM_RB25#0




Date: 17.DEC.2022 09:56:51

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 17.DEC.2022 09:57:12

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 17.DEC.2022 09:57:34

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 17.DEC.2022 09:57:51

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 17.DEC.2022 09:58:10

Band 4_10 MHz_High_QPSK_RB50#0




Date: 17.DEC.2022 09:58:30


Band 4_10 MHz_High_16QAM_RB50#0



Date: 17.DEC.2022 09:58:49




Date: 17.DEC.2022 09:59:09




Date: 17.DEC.2022 09:59:33

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 17.DEC.2022 09:59:55

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 17.DEC.2022 10:00:17

Band 4_15 MHz_High_QPSK_RB75#0




Date: 17.DEC.2022 10:00:36

Band 4_15 MHz_High_16QAM_RB75#0




Date: 17.DEC.2022 10:00:58

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 17.DEC.2022 10:01:24

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 17.DEC.2022 10:01:47

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 17.DEC.2022 10:02:10

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 17.DEC.2022 10:02:32

Band 4_20 MHz_High_QPSK_RB100#0




Date: 17.DEC.2022 10:02:52

Band 4_20 MHz_High_16QAM_RB100#0




Date: 17.DEC.2022 10:03:14

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 10:03:33

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 10:03:52

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 17.DEC.2022 10:04:11

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 17.DEC.2022 10:04:30

Band 7_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 10:04:49


Band 7_5 MHz_High_16QAM_RB25#0



Date: 17.DEC.2022 10:05:07




Date: 17.DEC.2022 10:05:28




Date: 17.DEC.2022 10:05:48

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 17.DEC.2022 10:06:07

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 17.DEC.2022 10:06:27

Band 7_10 MHz_High_QPSK_RB50#0



Date: 17.DEC.2022 10:06:47


Band 7_10 MHz_High_16QAM_RB50#0



Date: 17.DEC.2022 10:07:09


[illegible]

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 17.DEC.2022 10:07:50

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 17.DEC.2022 10:08:10

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 17.DEC.2022 10:08:29

Band 7_15 MHz_High_QPSK_RB75#0




Date: 17.DEC.2022 10:08:51

Band 7_15 MHz_High_16QAM_RB75#0




Date: 17.DEC.2022 10:09:12

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 17.DEC.2022 10:09:37

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 17.DEC.2022 10:09:59

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 17.DEC.2022 10:10:22

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 17.DEC.2022 10:10:44

Band 7_20 MHz_High_QPSK_RB100#0




Date: 17.DEC.2022 10:11:09

Band 7_20 MHz_High_16QAM_RB100#0




Date: 17.DEC.2022 10:11:32

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 1.DEC.2022 13:33:08

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 1.DEC.2022 13:33:27

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.DEC.2022 13:33:51

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.DEC.2022 13:34:17

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 1.DEC.2022 13:35:37

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 1.DEC.2022 13:35:58

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 1.DEC.2022 13:36:18

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 1.DEC.2022 13:36:43

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 1.DEC.2022 13:37:01

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 1.DEC.2022 13:37:19

Band 5_3 MHz_High_QPSK_RB15#0




Date: 1.DEC.2022 13:37:38

Band 5_3 MHz_High_16QAM_RB15#0




Date: 1.DEC.2022 13:37:56

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 1.DEC.2022 13:38:20

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 1.DEC.2022 13:38:38

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 1.DEC.2022 13:39:04

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 1.DEC.2022 13:39:26

Band 5_5 MHz_High_QPSK_RB25#0




Date: 1.DEC.2022 13:39:45

Band 5_5 MHz_High_16QAM_RB25#0




Date: 1.DEC.2022 13:40:04

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 1.DEC.2022 13:40:28

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 1.DEC.2022 13:40:47

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 1.DEC.2022 13:41:07

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 1.DEC.2022 13:41:26

Band 5_10 MHz_High_QPSK_RB50#0




Date: 1.DEC.2022 13:41:49

Band 5_10 MHz_High_16QAM_RB50#0




Date: 1.DEC.2022 13:42:08

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 1.DEC.2022 11:40:07

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 1.DEC.2022 11:40:36

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 1.DEC.2022 11:41:01

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 1.DEC.2022 11:41:23

Band 41_5 MHz_High_QPSK_RB25#0




Date: 1.DEC.2022 11:41:49

Band 41_5 MHz_High_16QAM_RB25#0




Date: 1.DEC.2022 11:42:14

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 1.DEC.2022 11:43:48

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 1.DEC.2022 11:44:07

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 1.DEC.2022 11:44:30

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 1.DEC.2022 11:44:49

Band 41_10 MHz_High_QPSK_RB50#0




Date: 1.DEC.2022 11:45:14

Band 41_10 MHz_High_16QAM_RB50#0




Date: 1.DEC.2022 11:45:39

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 1.DEC.2022 11:47:23

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 1.DEC.2022 11:47:45

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 1.DEC.2022 11:48:11

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 1.DEC.2022 11:48:36

Band 41_15 MHz_High_QPSK_RB75#0




Date: 1.DEC.2022 11:49:05

Band 41_15 MHz_High_16QAM_RB75#0




Date: 1.DEC.2022 11:49:27

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 1.DEC.2022 11:51:03

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 1.DEC.2022 11:51:30

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 1.DEC.2022 11:52:00

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 1.DEC.2022 11:52:32

Band 41_20 MHz_High_QPSK_RB100#0




Date: 1.DEC.2022 11:52:55

Band 41_20 MHz_High_16QAM_RB100#0




Date: 1.DEC.2022 11:53:17

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 9.JAN.2023 15:38:32

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 9.JAN.2023 15:39:01

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 9.JAN.2023 15:39:27

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 9.JAN.2023 15:39:48

Band 38_5 MHz_High_QPSK_RB25#0




Date: 9.JAN.2023 15:40:20

Band 38_5 MHz_High_16QAM_RB25#0




Date: 9.JAN.2023 15:40:42

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 9.JAN.2023 15:41:03

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 9.JAN.2023 15:41:26

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 9.JAN.2023 15:41:46

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 9.JAN.2023 15:42:06

Band 38_10 MHz_High_QPSK_RB50#0




Date: 9.JAN.2023 15:42:25

Band 38_10 MHz_High_16QAM_RB50#0




Date: 9.JAN.2023 15:42:45

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 9.JAN.2023 15:43:09

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 9.JAN.2023 15:43:31

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 9.JAN.2023 15:44:00

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 9.JAN.2023 15:44:25

Band 38_15 MHz_High_QPSK_RB75#0




Date: 9.JAN.2023 15:44:47

Band 38_15 MHz_High_16QAM_RB75#0




Date: 9.JAN.2023 15:45:09

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 9.JAN.2023 15:45:36

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 9.JAN.2023 15:46:05

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 9.JAN.2023 15:46:28

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 9.JAN.2023 15:46:50

Band 38_20 MHz_High_QPSK_RB100#0



Date: 9.JAN.2023 15:47:16

Band 38_20 MHz_High_16QAM_RB100#0



Date: 9.JAN.2023 15:47:41