




Freq. Stability 20C 2.81V a 5240MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V a 5240MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:03

Freq. Stability -20C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:11

Freq. Stability -10C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:18

Freq. Stability 0C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:25

Freq. Stability 10C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:33

Freq. Stability 30C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:47

Freq. Stability 40C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:11:54

Freq. Stability 50C 3.3V a 5240MHz Ant2 0 Minutes




Date: 21.09.2023 21:12:02

Freq. Stability 20C 2.81V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:01

Freq. Stability 20C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:32

Freq. Stability 20C 3.80V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:15

Freq. Stability -20C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:22

Freq. Stability -10C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:30

Freq. Stability 0C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:37

Freq. Stability 10C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:44

Freq. Stability 30C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:30:59

Freq. Stability 40C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:31:06

Freq. Stability 50C 3.3V a 5260MHz Ant2 0 Minutes




Date: 21.09.2023 21:31:14

Freq. Stability 20C 2.81V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:33:33

Freq. Stability 20C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:44

Freq. Stability 20C 3.80V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:08

Freq. Stability -20C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:15

Freq. Stability -10C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:22

Freq. Stability 0C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:30

Freq. Stability 10C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:37

Freq. Stability 30C 3.3V a 5300MHz Ant2 0 Minutes




Date: 21.09.2023 21:34:32


Freq. Stability 40C 3.3V a 5300MHz Ant2 0 Minutes



Freq. Stability 50C 3.3V a 5300MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:22:19

Freq. Stability 20C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:23:10

Freq. Stability 20C 3.80V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:22:33

Freq. Stability -20C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:22:40

Freq. Stability -10C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:22:48

Freq. Stability 0C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:22:55


Freq. Stability 10C 3.3V a 5320MHz Ant2 0 Minutes



Freq. Stability 30C 3.3V a 5320MHz Ant2 0 Minutes




Freq. Stability 40C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:23:24

Freq. Stability 50C 3.3V a 5320MHz Ant2 0 Minutes




Date: 22.09.2023 19:23:31


Freq. Stability 20C 2.81V a 5500MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V a 5500MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5500MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V a 5500MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V a 5500MHz Ant2 0 Minutes




Date: 22.09.2023 19:36:59

Freq. Stability 0C 3.3V a 5500MHz Ant2 0 Minutes




Date: 22.09.2023 19:37:06

Freq. Stability 10C 3.3V a 5500MHz Ant2 0 Minutes




Date: 22.09.2023 19:37:13

Freq. Stability 30C 3.3V a 5500MHz Ant2 0 Minutes




Date: 22.09.2023 19:37:28


Freq. Stability 40C 3.3V a 5500MHz Ant2 0 Minutes



Freq. Stability 50C 3.3V a 5500MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:39:37

Freq. Stability 20C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:40:48

Freq. Stability 20C 3.80V a 5600MHz Ant2 0 Minutes




Date: 22.09.2023 19:40:12

Freq. Stability -20C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.09.2023 19:40:19

Freq. Stability -10C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:40:26

Freq. Stability 0C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:40:34

Freq. Stability 10C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.09.2023 19:40:41

Freq. Stability 30C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.09.2023 19:40:55

Freq. Stability 40C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:41:03

Freq. Stability 50C 3.3V a 5600MHz Ant2 0 Minutes




Date: 22.9.2023 19:41:10


Freq. Stability 20C 2.81V a 5700MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V a 5700MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5700MHz Ant2 0 Minutes




Freq. Stability -20C 3.3V a 5700MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V a 5700MHz Ant2 0 Minutes




Freq. Stability 0C 3.3V a 5700MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V a 5700MHz Ant2 0 Minutes



Freq. Stability 30C 3.3V a 5700MHz Ant2 0 Minutes




Freq. Stability 40C 3.3V a 5700MHz Ant2 0 Minutes




Date: 22.9.2023 19:45:15

Freq. Stability 50C 3.3V a 5700MHz Ant2 0 Minutes




Date: 22.9.2023 19:45:22


Freq. Stability 20C 2.81V a 5745MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V a 5745MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5745MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V a 5745MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V a 5745MHz Ant2 0 Minutes




Date: 22.09.2023 19:48:37

Freq. Stability 0C 3.3V a 5745MHz Ant2 0 Minutes




Date: 22.09.2023 19:48:44

Freq. Stability 10C 3.3V a 5745MHz Ant2 0 Minutes




Date: 22.09.2023 19:48:32

Freq. Stability 30C 3.3V a 5745MHz Ant2 0 Minutes




Date: 22.09.2023 19:49:07


Freq. Stability 40C 3.3V a 5745MHz Ant2 0 Minutes




Freq. Stability 50C 3.3V a 5745MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V a 5785MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V a 5785MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5785MHz Ant2 0 Minutes




Date: 22.09.2023 19:51:32

Freq. Stability -20C 3.3V a 5785MHz Ant2 0 Minutes




Date: 22.09.2023 19:51:39


Freq. Stability -10C 3.3V a 5785MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V a 5785MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V a 5785MHz Ant2 0 Minutes




Date: 22.9.2023 19:52:21

Freq. Stability 30C 3.3V a 5785MHz Ant2 0 Minutes




Date: 22.9.2023 19:52:35


Freq. Stability 40C 3.3V a 5785MHz Ant2 0 Minutes




Freq. Stability 50C 3.3V a 5785MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V a 5825MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V a 5825MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V a 5825MHz Ant2 0 Minutes




Date: 22.09.2023 19:55:16

Freq. Stability -20C 3.3V a 5825MHz Ant2 0 Minutes




Date: 22.09.2023 19:55:23


Freq. Stability -10C 3.3V a 5825MHz Ant2 0 Minutes




Freq. Stability 0C 3.3V a 5825MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V a 5825MHz Ant2 0 Minutes



Freq. Stability 30C 3.3V a 5825MHz Ant2 0 Minutes




Freq. Stability 40C 3.3V a 5825MHz Ant2 0 Minutes




Date: 22.9.2023 19:56:07

Freq. Stability 50C 3.3V a 5825MHz Ant2 0 Minutes




Date: 22.9.2023 19:56:14


Freq. Stability 20C 2.81V n20 5180MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V n20 5180MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V n20 5180MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V n20 5180MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:08

Freq. Stability 0C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:16

Freq. Stability 10C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:23

Freq. Stability 30C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:38

Freq. Stability 40C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:45

Freq. Stability 50C 3.3V n20 5180MHz Ant1 0 Minutes




Date: 19.09.2023 23:51:52


Freq. Stability 20C 2.81V n20 5200MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V n20 5200MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V n20 5200MHz Ant1 0 Minutes




Date: 19.09.2023 25:55:07

Freq. Stability -20C 3.3V n20 5200MHz Ant1 0 Minutes




Date: 19.09.2023 25:55:14

Freq. Stability -10C 3.3V n20 5200MHz Ant1 0 Minutes




Date: 19.09.2023 23:55:22

Freq. Stability 0C 3.3V n20 5200MHz Ant1 0 Minutes




Date: 19.09.2023 23:55:29

Freq. Stability 10C 3.3V n20 5200MHz Ant1 0 Minutes



Freq. Stability 30C 3.3V n20 5200MHz Ant1 0 Minutes




Freq. Stability 40C 3.3V n20 5200MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.89 dB RBW 10 kHz
Att 30 dB SWT 40 ms VBW 30 kHz Mode Sweep

SGL Count 20/20

1Pk Max



Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.19998 GHz	-22.69 dBm		
M2	1		5.19108 GHz	-19.89 dBm		
M3	1		5.20888 GHz	-20.21 dBm		

Date: 19.07.2023 23:55:38


Freq. Stability 50C 3.3V n20 5200MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.89 dB RBW 10 kHz
Att 30 dB SWT 40 ms VBW 30 kHz Mode Sweep

SGL Count 20/20

1Pk Max



Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.19996 GHz	-24.47 dBm		
M2	1		5.19108 GHz	-19.33 dBm		
M3	1		5.20884 GHz	-16.26 dBm		

Date: 19.07.2023 23:56:05