





7. PHOTOS OF TESTING
A52. FLOPPY WHOLE VIEW




7. PHOTOS OF TESTING
A54. CD ROM WHOLE VIEW



7. PHOTOS OF TESTING
A53. CD ROM WHOLE VIEW



7. PHOTOS OF TESTING
A55. SDRAM WHOLE VIEW




7. PHOTOS OF TESTING

A56. HDD COMPONENT SIDE


A57. HDD TOP SIDE

HDD
SEAGATE
ST32111A 2.1GB



'98 731

HDD
SEAGATE
ST32111A 2.1GB



'98 731


7. PHOTOS OF TESTING
A58. HDD COMPONENT SIDE
A59. HDD TOP SIDE





7. PHOTOS OF TESTING

A60. HDD COMPONENT SIDE



A61. HDD TOP SIDE





7. PHOTOS OF TESTING
A62. HDD WHOLE VIEW





7. PHOTOS OF TESTING
A63. HDD WHOLE VIEW



7. PHOTOS OF TESTING
A64. RISER CARD COMPONENT SIDE
A65. RISER CARD SOLDER SIDE






7. PHOTOS OF TESTING
A66. RISER CARD COMPONENT SIDE
A67. RISER CARD SOLDER SIDE

IBM MX-300 225MHz


8G21



7. PHOTOS OF TESTING
A. MAIN BOARD COMPONENT SIDE VIEW

IBM MX-300 225MHz


8G21



7. PHOTOS OF TESTING
B. MAIN BOARD SOLDER SIDE VIEW

7. PHOTOS OF TESTING

C. MAIN BOARD COMPONENT SIDE VIEW



8G21

IBM MX-300 233MHz

'98