

Doc No. RF1812-032

Date : Dec. 11, 2018

Subject: Declaration letter

Dear Sirs,

We, Hyundai Mobis Co., Ltd., declare that below DISPLAY CAR SYSTEM contains a previously certified LTE/WCDMA module (FCC ID: LHJ-CASAN) does not operate simultaneously with Bluetooth.

[Product Information]

Company Name: Hyundai Mobis Co., Ltd.

FCC ID: TQ8-ATBB0G2AN1

Model Number: ATBB0G2AN_NOWIFI, ATBB0G7AN_NOWIFI, ADB41G2AN_NOWIFI

The LTE/WCDMA function is mainly Navigation & E-call support. Once the Bluetooth operates during LTE/WCDMA operation, the display UI is changed to Bluetooth and it stopped to support LTE/WCDMA. Thus reason, LTE/WCDMA and Bluetooth is not simultaneously operated.

Sincerely yours,



Seung-Hoon Choe
/Representative
/Hyundai Mobis Co., Ltd.