

Ericsson Wireless Communications, Inc 6455 Lusk Blvd. San Diego, CA 92121-2779

Ph: (619) 658-4534 FAX: (619) 658-2120 E-mail: dkimball@qualcomm.com

Re: FCC ID OJYDFK1

Applicant: Ericsson Wireless Communications

Correspondence Reference Number: 7887
731 Confirmation Number: EA94207
Date of Original E-Mail: 05/21/1999

June 15, 2001

Federal Communications Commission
OET Laboratory Division Electronic Filing Site
<a href="https://gullfoss.fcc.gov/prod/oet/index.html">https://gullfoss.fcc.gov/prod/oet/index.html</a>

Dear Sir or Madam:

Qualcomm, Inc. Wireless Infrastructure Division was purchased by Ericsson Wireless Communications, Inc. effective May 24, 1999. I was Qualcomm's infrastructure regulatory manager and I have transferred to Ericsson. We are requesting a change in the FCC ID for the former Qualcomm 800MHz and 1900MHz base stations and pilot beacons. The 3 character prefix is being changed from J9C (Qualcomm) to OJY (Ericsson).

This request is for FCC ID OJYDFK1, a 1900MHz cellular base station. The design of the base stations and pilot beacons are unchanged. In addition, the manufacturing location, equipment, processes, and personal remain unchanged. However, we will be changing the branding, trade dress, and model numbers to Ericsson's corporate standards.

The following exhibits are attached, and a separate electronic submission will be made for each FCC ID.

Exhibit 1: FCC ID Change Matrix

Exhibit 2: FCC ID Label

Exhibit 3: Photograph showing location of FCC ID label

Exhibit 4: Rear View of Base Station Exhibit 5: Front View of Base Station

Sincerely,

Donald F. Kimball Regulatory Senior Staff Engineer/Manager • Page 2 June 15, 2001

## **Exhibit 1: FCC ID Change Matrix**

Qualcomm	Qualcomm	Original Grant	Ericsson Model	Ericsson	FCC
Model Number	FCC ID	Date	Number	FCC ID	Application No.
Base Stations					
QCell 2508i	J9CJAY1	07/10/96	RBS 1102 800	OJYJAY1	EA94134
QCell 2519e	J9CJAY2	03/03/98	RBS 1102 1900	OJYJAY2	EA94122
QCell 3508i	J9CDFK2	02/11/98	RBS 1103 800	OJYDFK2	EA94206
QCell 3519i	J9CDFK1	06/02/98	RBS 1103 1900	OJYDFK1	EA94207
QCell 619e	J9CKAG4	04/20/99	RBS 1106 1900	OJYKAG4	EA94209
Pilot Beacons					
QCPB 800i	J9CKAG1	04/07/97	CMS 11 800i	OJYKAG1	EA94210
QCPB 1900e	J9CKAG2	08/01/97	CMS 11 1900e	OJYKAG2	EA94211
QCPB 800e	J9CKAG3	01/21/98	CMS 11 800e	OJYKAG3	EA94212

• Page 3 June 15, 2001



## Exhibit 2 FCC ID Label, OJYDFK1, Click to Display

• Page 4 June 15, 2001

FCC ID Label Location, OJYDFK1



**Exhibit 3 FCC ID Label Location, OJYDFK1** 

• Page 5 June 15, 2001

## FCC ID Label Locations, OJYDFK1



Exhibit 4 Rear View, OJYDFK1

• Page 6 June 15, 2001



Exhibit 5 Front View, OJYDFK1

• Page 7 June 15, 2001