



Please refer to following plots:


Band 2_1.4 MHz_Low_QPSK_RB6#0



Band 2_1.4 MHz_Low_16QAM_RB6#0




Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 10.MAR.2022 16:37:36

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 10.MAR.2022 16:37:55

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 10.MAR.2022 16:38:19

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 10.MAR.2022 16:38:35

Band 2_3 MHz_High_QPSK_RB15#0




Date: 10.MAR.2022 16:38:54

Band 2_3 MHz_High_16QAM_RB15#0




Date: 10.MAR.2022 16:39:12

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 10.MAR.2022 16:39:36

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 10.MAR.2022 16:40:08

Band 2_5 MHz_High_QPSK_RB25#0




Date: 10.MAR.2022 16:41:23

Band 2_5 MHz_High_16QAM_RB25#0




Date: 10.MAR.2022 16:41:42

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 10.MAR.2022 16:42:09

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 10.MAR.2022 16:42:33

Band 2_10 MHz_High_QPSK_RB50#0




Date: 10.MAR.2022 16:43:00

Band 2_10 MHz_High_16QAM_RB50#0




Date: 10.MAR.2022 16:43:29

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 10.MAR.2022 16:44:03

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 10.MAR.2022 16:44:35

Band 2_15 MHz_High_QPSK_RB75#0




Date: 10.MAR.2022 16:45:00

Band 2_15 MHz_High_16QAM_RB75#0




Date: 10.MAR.2022 16:45:34

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 10.MAR.2022 16:46:12

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 10.MAR.2022 16:46:43

Band 2_20 MHz_High_QPSK_RB100#0




Date: 10.MAR.2022 16:47:22

Band 2_20 MHz_High_16QAM_RB100#0




Date: 10.MAR.2022 16:47:52

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 10.MAR.2022 16:48:20

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 10.MAR.2022 16:48:41

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 10.MAR.2022 16:49:12

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 10.MAR.2022 16:49:37

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 10.MAR.2022 16:49:57

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 10.MAR.2022 16:50:15

Band 4_3 MHz_High_QPSK_RB15#0




Date: 10.MAR.2022 16:50:37

Band 4_3 MHz_High_16QAM_RB15#0




Date: 10.MAR.2022 16:50:52

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 10.MAR.2022 16:51:16

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 10.MAR.2022 16:51:37

Band 4_5 MHz_High_QPSK_RB25#0




Date: 10.MAR.2022 16:51:56

Band 4_5 MHz_High_16QAM_RB25#0




Date: 10.MAR.2022 16:52:14

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 10.MAR.2022 16:52:39

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 10.MAR.2022 16:53:09

Band 4_10 MHz_High_QPSK_RB50#0




Date: 10.MAR.2022 16:53:38

Band 4_10 MHz_High_16QAM_RB50#0




Date: 10.MAR.2022 16:54:07

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 10.MAR.2022 16:54:41

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 10.MAR.2022 16:55:15

Band 4_15 MHz_High_QPSK_RB75#0




Date: 10.MAR.2022 16:55:47

Band 4_15 MHz_High_16QAM_RB75#0




Date: 10.MAR.2022 16:56:15

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 10.MAR.2022 16:57:25

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 10.MAR.2022 16:58:00

Band 4_20 MHz_High_QPSK_RB100#0




Date: 10.MAR.2022 16:58:32

Band 4_20 MHz_High_16QAM_RB100#0




Date: 10.MAR.2022 16:59:01

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 10.MAR.2022 16:59:21

Band 5_1.4 MHz_Low_16QAM_RB6#0



Date: 10.MAR.2022 16:59:36

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 11.MAR.2022 10:49:07

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 11.MAR.2022 10:50:05

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 11.MAR.2022 10:51:14

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 11.MAR.2022 10:51:53

Band 5_3 MHz_High_QPSK_RB15#0




Date: 11.MAR.2022 10:53:19

Band 5_3 MHz_High_16QAM_RB15#0




Date: 11.MAR.2022 10:54:00

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 11.MAR.2022 10:56:01

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 11.MAR.2022 10:56:57

Band 5_5 MHz_High_QPSK_RB25#0




Date: 11.MAR.2022 10:58:42

Band 5_5 MHz_High_16QAM_RB25#0




Date: 11.MAR.2022 10:59:39

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 10.MAR.2022 17:04:25

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 10.MAR.2022 17:04:54

Band 5_10 MHz_High_QPSK_RB50#0




Date: 10.MAR.2022 17:05:21

Band 5_10 MHz_High_16QAM_RB50#0




Date: 10.MAR.2022 17:05:43

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 10.MAR.2022 17:06:08

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 10.MAR.2022 17:06:30

Band 7_5 MHz_High_QPSK_RB25#0




Date: 10.MAR.2022 17:06:56

Band 7_5 MHz_High_16QAM_RB25#0




Date: 10.MAR.2022 17:07:14

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 10.MAR.2022 17:07:43

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 10.MAR.2022 17:08:15

Band 7_10 MHz_High_QPSK_RB50#0




Date: 10.MAR.2022 17:08:39

Band 7_10 MHz_High_16QAM_RB50#0




Date: 10.MAR.2022 17:09:11

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 10.MAR.2022 17:09:45

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 10.MAR.2022 17:10:16

Band 7_15 MHz_High_QPSK_RB75#0




Date: 10.MAR.2022 17:10:48

Band 7_15 MHz_High_16QAM_RB75#0




Date: 10.MAR.2022 17:11:26

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 10.MAR.2022 17:12:14

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 10.MAR.2022 17:12:45

Band 7_20 MHz_High_QPSK_RB100#0




Date: 10.MAR.2022 17:13:18

Band 7_20 MHz_High_16QAM_RB100#0




Date: 10.MAR.2022 17:13:46

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 11.MAR.2022 09:20:31

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 11.MAR.2022 10:40:18

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.MAR.2022 09:21:04

Band 38_5 MHz_High_16QAM_RB25#0




Date: 11.MAR.2022 09:21:21

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 11.MAR.2022 09:21:41

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 11.MAR.2022 09:22:00

Band 38_10 MHz_High_QPSK_RB50#0




Date: 11.MAR.2022 09:22:26

Band 38_10 MHz_High_16QAM_RB50#0




Date: 11.MAR.2022 09:22:48

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 11.MAR.2022 09:23:14

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 11.MAR.2022 09:23:39

Band 38_15 MHz_High_QPSK_RB75#0




Date: 11.MAR.2022 09:24:00

Band 38_15 MHz_High_16QAM_RB75#0




Date: 11.MAR.2022 09:24:25

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 11.MAR.2022 09:25:01

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 11.MAR.2022 09:25:32

Band 38_20 MHz_High_QPSK_RB100#0




Date: 11.MAR.2022 09:26:13

Band 38_20 MHz_High_16QAM_RB100#0




Date: 11.MAR.2022 09:26:41

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 11.MAR.2022 10:13:28

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 11.MAR.2022 10:37:50

Band 41_5 MHz_High_QPSK_RB25#0




Date: 11.MAR.2022 10:14:07

Band 41_5 MHz_High_16QAM_RB25#0




Date: 11.MAR.2022 10:14:32

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 11.MAR.2022 10:14:52

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 11.MAR.2022 10:15:11

Band 41_10 MHz_High_QPSK_RB50#0




Date: 11.MAR.2022 10:15:30

Band 41_10 MHz_High_16QAM_RB50#0




Date: 11.MAR.2022 10:15:49

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 11.MAR.2022 10:16:11

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 11.MAR.2022 10:16:36

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.MAR.2022 10:17:01

Band 41_15 MHz_High_16QAM_RB75#0




Date: 11.MAR.2022 10:17:22

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 11.MAR.2022 10:17:58

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 11.MAR.2022 10:18:19

Band 41_20 MHz_High_QPSK_RB100#0



Date: 11.MAR.2022 10:18:48

Band 41_20 MHz_High_16QAM_RB100#0



Date: 11.MAR.2022 10:19:25