





Band41-10MHz-16QAM-40365-50RB#0



Band41-10MHz-16QAM-40690-50RB#0




Band41-10MHz-16QAM-41115-50RB#0

Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com


Hotline
400-003-0500
www.anbotech.com



Band41-15MHz-QPSK-40415-75RB#0



Band41-15MHz-QPSK-40690-75RB#0




Band41-15MHz-QPSK-41065-75RB#0

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com


Hotline
400-003-0500
www.anbotek.com



Band41-15MHz-16QAM-40415-75RB#0



Band41-15MHz-16QAM-40690-75RB#0




Band41-15MHz-16QAM-41065-75RB#0

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com



Band41-20MHz-QPSK-40440-100RB#0



Band41-20MHz-QPSK-40690-100RB#0




Band41-20MHz-QPSK-41040-100RB#0

Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com

Hotline
400-003-0500
www.anbotech.com



Band41-20MHz-16QAM-40440-100RB#0



Band41-20MHz-16QAM-40690-100RB#0



Band41-20MHz-16QAM-41040-100RB#0



Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com

Appendix D: Band Edge

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dBm)	Verdict
Band41	5MHz	QPSK	40365	1RB#0	-59.70,-47.6 7,-39.72,-23 .33	PASS
Band41	5MHz	QPSK	40365	1RB#24	-59.59,-56.2 1,-33.67,-46 .05	PASS
Band41	5MHz	QPSK	40365	25RB#0	-57.65,-52.2 4,-36.97,-32 .64	PASS
Band41	5MHz	QPSK	41115	1RB#0	-45.90,-31.5 7,-53.34,-58 .83	PASS
Band41	5MHz	QPSK	41115	1RB#24	-23.76,-36.5 9,-45.84,-58 .71	PASS
Band41	5MHz	QPSK	41115	25RB#0	-29.96,-34.8 1,-49.05,-54 .74	PASS
Band41	5MHz	16QAM	40365	1RB#0	-48.45,-50.5 6,-39.84,-25 .68	PASS
Band41	5MHz	16QAM	40365	1RB#24	-59.38,-56.0 6,-35.99,-49 .83	PASS
Band41	5MHz	16QAM	40365	25RB#0	-57.01,-51.3 7,-36.90,-34 .03	PASS
Band41	5MHz	16QAM	41115	1RB#0	-45.14,-31.5 0,-52.23,-58 .48	PASS
Band41	5MHz	16QAM	41115	1RB#24	-24.32,-36.0 9,-46.22,-58 .68	PASS
Band41	5MHz	16QAM	41115	25RB#0	-31.79,-34.0 2,-49.19,-54 .31	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Band41	10MHz	QPSK	40390	1RB#0	-51.54,-45.8 1,-35.59,-25 .23	PASS
Band41	10MHz	QPSK	40390	1RB#49	-57.19,-34.8 0,-50.54,-50 .26	PASS
Band41	10MHz	QPSK	40390	50RB#0	-53.16,-41.6 9,-36.62,-35 .31	PASS
Band41	10MHz	QPSK	41090	1RB#0	-47.38,-48.1 2,-28.68,-55 .64	PASS
Band41	10MHz	QPSK	41090	1RB#49	-24.83,-34.2 7,-44.22,-53 .61	PASS
Band41	10MHz	QPSK	41090	50RB#0	-31.99,-34.1 3,-37.78,-48 .74	PASS
Band41	10MHz	16QAM	40390	1RB#0	-52.10,-48.4 1,-39.43,-25 .17	PASS
Band41	10MHz	16QAM	40390	1RB#49	-57.33,-35.2 1,-53.75,-52 .11	PASS
Band41	10MHz	16QAM	40390	50RB#0	-53.40,-41.4 6,-36.99,-33 .98	PASS
Band41	10MHz	16QAM	41090	1RB#0	-47.24,-48.0 6,-27.15,-54 .77	PASS
Band41	10MHz	16QAM	41090	1RB#49	-25.03,-33.9 2,-43.48,-52 .83	PASS
Band41	10MHz	16QAM	41090	50RB#0	-31.59,-32.6 3,-38.04,-48 .88	PASS
Band41	15MHz	QPSK	40415	1RB#0	-54.75,-45.8 9,-35.51,-27 .49	PASS
Band41	15MHz	QPSK	40415	1RB#74	-55.70,-33.7 9,-52.95,-52 .22	PASS
Band41	15MHz	QPSK	40415	75RB#0	-51.93,-39.4 2,-36.10,-35	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

					.31	
Band41	15MHz	QPSK	41065	1RB#0	-49.58,-49.3 2,-26.75,-54	PASS
					.27	
Band41	15MHz	QPSK	41065	1RB#74	-27.23,-36.0 6,-44.95,-54	PASS
					.07	
Band41	15MHz	QPSK	41065	75RB#0	-32.78,-31.9 7,-34.75,-47	PASS
					.50	
Band41	15MHz	16QAM	40415	1RB#0	-55.27,-47.6 7,-37.67,-29	PASS
					.59	
Band41	15MHz	16QAM	40415	1RB#74	-55.90,-34.5 1,-54.31,-53	PASS
					.12	
Band41	15MHz	16QAM	40415	75RB#0	-52.63,-39.8 8,-36.26,-35	PASS
					.80	
Band41	15MHz	16QAM	41065	1RB#0	-48.55,-49.1 4,-26.57,-54	PASS
					.20	
Band41	15MHz	16QAM	41065	1RB#74	-26.14,-34.0 1,-42.98,-53	PASS
					.41	
Band41	15MHz	16QAM	41065	75RB#0	-32.78,-32.5 2,-35.18,-48	PASS
					.26	
Band41	20MHz	QPSK	40440	1RB#0	-54.81,-44.2 0,-34.56,-29	PASS
					.24	
Band41	20MHz	QPSK	40440	1RB#99	-55.00,-36.3 7,-52.60,-51	PASS
					.91	
Band41	20MHz	QPSK	40440	100RB#0	-53.13,-39.5 5,-36.43,-35	PASS
					.12	
Band41	20MHz	QPSK	41040	1RB#0	-49.99,-49.9 5,-26.81,-54	PASS
					.01	
Band41	20MHz	QPSK	41040	1RB#99	-29.82,-36.3 4,-44.18,-53	PASS
					.25	
Band41	20MHz	QPSK	41040	100RB#0	-32.78,-33.3	PASS

Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com




Hotline

400-003-0500

www.anbotech.com

					4,-34.55,-49 .04	
Band41	20MHz	16QAM	40440	1RB#0	-54.23,-43.2 0,-34.01,-26 .96	PASS
Band41	20MHz	16QAM	40440	1RB#99	-55.03,-37.6 3,-51.82,-51 .03	PASS
Band41	20MHz	16QAM	40440	100RB#0	-53.14,-39.9 8,-37.23,-35 .86	PASS
Band41	20MHz	16QAM	41040	1RB#0	-50.66,-49.8 1,-26.65,-53 .85	PASS
Band41	20MHz	16QAM	41040	1RB#99	-29.44,-36.5 5,-44.33,-53 .61	PASS
Band41	20MHz	16QAM	41040	100RB#0	-33.17,-33.7 4,-34.76,-49 .41	PASS

Test Graphs






Band41-5MHz-QPSK-40365-25RB#0



Band41-5MHz-QPSK-41115-1RB#0



Band41-5MHz-QPSK-41115-1RB#24

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com



Band41-5MHz-QPSK-41115-25RB#0



Band41-5MHz-16QAM-40365-1RB#0



Band41-5MHz-16QAM-40365-1RB#24

Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com



Band41-5MHz-16QAM-40365-25RB#0



Band41-5MHz-16QAM-41115-1RB#0



Band41-5MHz-16QAM-41115-1RB#24

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com


Hotline
400-003-0500
www.anbotek.com



Band41-5MHz-16QAM-41115-25RB#0



Band41-10MHz-QPSK-40390-1RB#0



Band41-10MHz-QPSK-40390-1RB#49

Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline
400-003-0500
www.anbotek.com