

EXHIBIT B

DESCRIPTION OF MODIFICATIONS



**Retlif Testing Laboratories**

Test Report Number R-7482  
FCC ID: B4SHP564A

FCC ID: B4SHP564A: DESCRIPTION OF MODIFICATIONS:

The following is a description of the changes made to the device:

The main difference between the Model HP564B and the previous version HP564A, is that the layout of the PCB was changed in order to accommodate a new IC.

The IC on the previous Model HP564A was an 18 Pin IC, P/N: PIC 16C54. The new IC on Model HP564B is an 8 Pin IC, P/N: PIC 12C508.

There were no changes to the RF section of the PCB layout.



**Retlif Testing Laboratories**

Test Report Number R-7482  
FCC ID: B4SHP564A