






Band4_1.4MHz_16QAM_20393_1RB#5_1000~3000_1000~3000



Band4_1.4MHz_16QAM_20393_1RB#5_3000~20000_3000~20000




Band4_1.4MHz_QPSK_20393_6RB#0_0.009~0.15_0.009~0.15



Band4_1.4MHz_QPSK_20393_6RB#0_0.15~30_0.15~30




Band4_1.4MHz_QPSK_20393_6RB#0_30~1000_30~1000




Band4_1.4MHz_QPSK_20393_6RB#0_1000~3000_1000~3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_1.4MHz_QPSK_20393_6RB#0_3000~20000_3000~20000



Band4_1.4MHz_16QAM_20393_6RB#0_0.009~0.15_0.009~0.15




Band4_1.4MHz_16QAM_20393_6RB#0_0.15~30_0.15~30



Band4_1.4MHz_16QAM_20393_6RB#0_30~1000_30~1000



Band4_1.4MHz_16QAM_20393_6RB#0_1000~3000_1000~3000




Band4_1.4MHz_16QAM_20393_6RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band4_3MHz_QPSK_19965_1RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_QPSK_19965_1RB#0_0.15~30_0.15~30




Band4_3MHz_QPSK_19965_1RB#0_30~1000_30~1000



Band4_3MHz_QPSK_19965_1RB#0_1000~3000_1000~3000




Band4_3MHz_QPSK_19965_1RB#0_3000~20000_3000~20000




Band4_3MHz_16QAM_19965_1RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_16QAM_19965_1RB#0_0.15-30_0.15-30




Band4_3MHz_16QAM_19965_1RB#0_30-1000_30-1000




Band4_3MHz_16QAM_19965_1RB#0_1000-3000_1000-3000



Band4_3MHz_16QAM_19965_1RB#0_3000-20000_3000-20000




Band4_3MHz_QPSK_19965_1RB#14_0.009-0.15_0.009-0.15



Band4_3MHz_QPSK_19965_1RB#14_0.15-30_0.15-30


Any report having not been signed by authorized approver, or having not been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band4_3MHz_QPSK_19965_1RB#14_30~1000_30~1000




Band4_3MHz_QPSK_19965_1RB#14_1000~3000_1000~3000



Band4_3MHz_QPSK_19965_1RB#14_3000~20000_3000~20000



Band4_3MHz_16QAM_19965_1RB#14_0.009~0.15_0.009~0.15



Band4_3MHz_16QAM_19965_1RB#14_0.15~30_0.15~30




Band4_3MHz_16QAM_19965_1RB#14_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_16QAM_19965_1RB#14_1000~3000_1000~3000




Band4_3MHz_16QAM_19965_1RB#14_3000~20000_3000~20000




Band4_3MHz_QPSK_19965_15RB#0_0.009~0.15_0.009~0.15



Band4_3MHz_QPSK_19965_15RB#0_0.15~30_0.15~30




Band4_3MHz_QPSK_19965_15RB#0_30~1000_30~1000




Band4_3MHz_QPSK_19965_15RB#0_1000~3000_1000~3000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band4_3MHz_QPSK_19965_15RB#0_3000~20000_3000~20000



Band4_3MHz_16QAM_19965_15RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_16QAM_19965_15RB#0_0.15~30_0.15~30



Band4_3MHz_16QAM_19965_15RB#0_30~1000_30~1000




Band4_3MHz_16QAM_19965_15RB#0_1000~3000_1000~3000




Band4_3MHz_16QAM_19965_15RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_QPSK_20175_1RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_QPSK_20175_1RB#0_0.15~30_0.15~30




Band4_3MHz_QPSK_20175_1RB#0_30~1000_30~1000



Band4_3MHz_QPSK_20175_1RB#0_1000~3000_1000~3000




Band4_3MHz_QPSK_20175_1RB#0_3000~20000_3000~20000



Band4_3MHz_16QAM_20175_1RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15 days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_16QAM_20175_1RB#0_0.15-30_0.15-30




Band4_3MHz_16QAM_20175_1RB#0_30-1000_30-1000




Band4_3MHz_16QAM_20175_1RB#0_1000-3000_1000-3000



Band4_3MHz_16QAM_20175_1RB#0_3000-20000_3000-20000




Band4_3MHz_QPSK_20175_1RB#14_0.009-0.15_0.009-0.15



Band4_3MHz_QPSK_20175_1RB#14_0.15-30_0.15-30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band4_3MHz_QPSK_20175_1RB#14_30~1000_30~1000




Band4_3MHz_QPSK_20175_1RB#14_1000~3000_1000~3000




Band4_3MHz_QPSK_20175_1RB#14_3000~20000_3000~20000



Band4_3MHz_16QAM_20175_1RB#14_0.009~0.15_0.009~0.15




Band4_3MHz_16QAM_20175_1RB#14_0.15~30_0.15~30




Band4_3MHz_16QAM_20175_1RB#14_30~1000_30~1000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_QPSK_20175_15RB#0_3000~20000_3000~20000




Band4_3MHz_16QAM_20175_15RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_16QAM_20175_15RB#0_0.15~30_0.15~30



Band4_3MHz_16QAM_20175_15RB#0_30~1000_30~1000



Band4_3MHz_16QAM_20175_15RB#0_1000~3000_1000~3000




Band4_3MHz_16QAM_20175_15RB#0_3000~20000_3000~20000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_QPSK_20385_1RB#0_0.009~0.15_0.009~0.15




Band4_3MHz_QPSK_20385_1RB#0_0.15~30_0.15~30




Band4_3MHz_QPSK_20385_1RB#0_30~1000_30~1000



Band4_3MHz_QPSK_20385_1RB#0_1000~3000_1000~3000




Band4_3MHz_QPSK_20385_1RB#0_3000~20000_3000~20000




Band4_3MHz_16QAM_20385_1RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>




Band4_3MHz_16QAM_20385_1RB#0_0.15-30_0.15-30




Band4_3MHz_16QAM_20385_1RB#0_30-1000_30-1000




Band4_3MHz_16QAM_20385_1RB#0_1000-3000_1000-3000



Band4_3MHz_16QAM_20385_1RB#0_3000-20000_3000-20000




Band4_3MHz_QPSK_20385_1RB#14_0.009-0.15_0.009-0.15




Band4_3MHz_QPSK_20385_1RB#14_0.15-30_0.15-30


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band4_3MHz_QPSK_20385_1RB#14_30~1000_30~1000




Band4_3MHz_QPSK_20385_1RB#14_1000~3000_1000~3000



Band4_3MHz_QPSK_20385_1RB#14_3000~20000_3000~20000



Band4_3MHz_16QAM_20385_1RB#14_0.009~0.15_0.009~0.15



Band4_3MHz_16QAM_20385_1RB#14_0.15~30_0.15~30



Band4_3MHz_16QAM_20385_1RB#14_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.