

Date: April 20, 2015

FCC ID: T68-FT400

Regarding: Request for Class II permissive change.

Please be notified that the Fluke Corporation declares that the reason for this class II permissive change is as described below:

1. A change to the system firmware to expand Bluetooth support to include Bluetooth Low Energy (BLE) operating modes in addition to the previously available Bluetooth classic operating modes. No changes are made to any part of the system hardware.
2. A change to the system firmware to expand WLAN support to include 802.11n operating modes in addition to the previously available 802.11b/g operating modes. No changes are made to any part of the system hardware.

Thank you very much for your attention to this matter.

Best Regards,



Signature

Name: James Lenker

Title: Product Compliance Engineer