

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 Phone 408 526-4000 Fax: 408 526 -4100 http://www.cisco.com

May 19, 2016

FCC ID: LDK7925G0269 CP-7925G

Submit a permissive Change to FCC Grant FCC ID: LDK7925G0269

This Device was previously authorized under 15.247 to be modified to operate under the New Rules and technical requirements of 15.407 (b) (4) (i) with no changes in total power except in the UNII – 3 band. This Device will be sold after 2020.