

MODULE PAD ASSIGNMENT

(TOP VIEW)

VCC
GND
PWM1
PWM2
PWM3
PWM4
ADC

1 7


(BOTTOM VIEW)

RF TEST PIN
GND
PUART_TX
PUART_RX
XRES
UART_TXD
UART_RXD
UART_CTS_N
UART_RTS_N

7 1

FOR SOLDER
FOR TEST

FOR DEBUG
FOR PROGRAM and HCI



Cypress Semiconductor Corp.			
Title CYBLE-413149/473148-01			
Size B	Document Number		Rev 1.1
Date:	2017WW13	Sheet	1 of 1