

FUJITSU ISOTEC LIMITED
FCC ID : KHZ0142348


Manufacturing drawing of FCC label

For Parallel + USB INF No LAN)

 TallyGenicom® TallyGenicom 4500 Daly Drive, Suite 100 Chantilly, VA 20151, USA Serial No.	Model No. 2348 ID. No. 234800-CA Volts: AC100-120V~ Hertz: 50/60Hz Amps: 1.2A	 NRTL/C 172997 	FCC ID:KHZ0142348 This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation. This Class B digital apparatus meets all requirements of the Canadian Interference-Causing Equipment Regulations. Cet appareil numérique de la classe B respecte toutes les exigences du Règlement sur le matériel brouilleur du Canada. MADE IN CHINA FABRIQUE EN CHINE
--	---	--	---

For Parallel + RS232C INF)

 TallyGenicom® TallyGenicom 4500 Daly Drive, Suite 100 Chantilly, VA 20151, USA Serial No.	Model No. 2348 ID. No. 234803-CA Volts: AC100-120V~ Hertz: 50/60Hz Amps: 1.2A	 NRTL/C 172997 	FCC ID:KHZ0142348 This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation. This Class B digital apparatus meets all requirements of the Canadian Interference-Causing Equipment Regulations. Cet appareil numérique de la classe B respecte toutes les exigences du Règlement sur le matériel brouilleur du Canada. MADE IN CHINA FABRIQUE EN CHINE
--	---	--	---



Label