

Company: MikroTik

Product Name: hAP ac²


Report No.: MIKO65 – Internal Photos

PHOTOS - INTERNAL




1. Internal Photographs

1.1.1. Product - Internal




Module - Bottom Side



Module - Bottom Side - Cans Removed



Title: MIKO65 Internal Photos
To:
Serial #:
Issue Date: 11 December 2017
Page: 4 of 6



Module - Top Side

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

Title: MIKO65 Internal Photos
To:
Serial #:
Issue Date: 11 December 2017
Page: 5 of 6



Module - Top Side - Heat Sink Removed

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com