




Test up photo



Description of the measurement method



1. The object to be measured emits electromagnetic waves
2. Receive probe receives electromagnetic waves
3. DUT- Measure the transfer strength between probes
4. The rotating arm and platform rotate and measure the global radiation pattern by performing 1~3 at each angle.