

# Appendix C. Set up Photograph

# **Conducted Emission**



# FRONT VIEW




# **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Oct. 07, 2005
Report Version : Rev. 01

Report No. : FR541416





SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3

Report Issued Date : Oct. 07, 2005

Report Version : Rev. 01






#### **Radiation Emission**



## **FRONT VIEW**



### **REAR VIEW**

#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Report Issued Date : Oct. 07, 2005
Report Version : Rev. 01