



5200 Auto Club Dr.
Dearborn, MI 48126
(313) 593-9000

Date: April 16, 2002

Re: Certification for Lear Corporation, Transmitter Model RLC-X and RLC-C+.

Description of Changes

For the following modules:

| Model | FCC ID | Canada ID |
|---------------|---------------|------------------|
| RLC-X, RLC-C+ | KOBLEAR1XT | 3521 102 1718 |

The following changes were made:

Moved capacitor C3.
Antenna layout changed.
Changed vendors for the SAW resonator.
Changed vendors for some of the capacitors.