



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101


August 8, 2006

RE: Proxim Corporation

FCC ID: HZB-4000LR

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Previous response to 3 appears inconsistent with 2 most recent 802.11b/g reports provided. See below:



- 2) Frequencies between manual and test data/731 form are still inconsistent and it is uncertain what is correct. For instance, the manual cites 5745 – 5825, while 731 form cites 5740 – 5835 MHz. Testing appears to suggest both 5740 – 5835 and 5760 – 5815. What is the true center frequencies? Is manual correct? Please review.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.