


EMC Technologies Report Number: M050750_Cert_WLL4070_DTS_BT

**APPENDIX K1
Harmonics - Atheros 802.11a**



Harmonics – Channel 149

Ref Lvl	15 dBm	Marker 2 [T1]	3.83166333 GHz	RBW	100 kHz	RF Att	30 dB
			-44.18 dBm	VBW	300 kHz		
				SWT	9.8 s	Unit	dBm




Date: 16.AUG.2005 16:22:39



Harmonics - Channel 165

Marker 2 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -42.36 dBm VBW 300 kHz
15 dBm 3.83166333 GHz SWT 9.8 s Unit dBm




Date: 16.AUG.2005 16:17:21



Harmonics - Channel 152 (Turbo)


Marker 2 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -42.21 dBm VBW 300 kHz
15 dBm 3.83166333 GHz SWT 9.8 s Unit dBm



Date: 16.AUG.2005 16:10:55

Harmonics - Channel 160 (Turbo)





Date: 16.AUG.2005 16:14:37

