

HTC Corporation

1F, 6-3 Baoqiang Road, Xindian District, New Taipei City 231, Taiwan

Tel: 886289124138 ; Fax: 886289126307


Date: September 29, 2014

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: NM80PFH100

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: NM80PFH100 to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,



Vincent Jou

Vincent_Jou@htc.com