



August 22, 2003

Federal Communication Commission
Equipment Approval Services, P.O. Box 358315
Pittsburgh, PA 15251-5315
Attention: Authorization & Evaluation Division

RE: Application for Vehicle Level Certification of Johnson Controls Transmitter under 47 CFR 15.231.
FCC ID: ACTLHL3

To whom it may concern,

Submitted here are materials for your consideration in determining the grant of certification for a Class II permissive change to the Johnson Controls Interior, LLC, Universal Garage Door Opener product. The FCC ID for this product is CB2ACTLHL3. The change being requested is a "vehicle level" Class II certification, negotiated by the Prince Corporation (later acquired by Johnson Controls Interiors) of Holland, MI. Correspondence between Prince Corporations and the FCC in regard to this testing methodology. A copy of the correspondence regarding this method and a summary of the procedure are available in the attachment "vehicle_level.pdf".

This submission is a request for a Class II change. The change made to this device is a change in the software controlled power settings. The change to these non-volatile memory values were approved for use in the Acura TL automobile in a previous submission (Form 731 confirmation #EA504983). The purpose of this report is to notify the commission that Johnson Controls intends to mount the same module in a different vehicle, the Acura MDX automobile. The only change to this report was to section "7.4.1.7 390 MHz Vehicle Level". The measurements in this section were taken with the CB2ACTLHL3 mounted in the Acura MDX automobile at 10m on the JCI OATS.

As stated in the original grant (Form 731 confirmation #0200587F), the JCI Model CB2ACTLHL3 is part of the Homelink ® III series. Homelink ® III devices are capable of learning garage door opener frequencies and codes from the user's original transmitter. The device is capable of learning in the range between 288MHz and 420MHz excluding forbidden frequency regions.

Johnson Controls Interiors has invested considerable resources into developing our Homelink ® products. For this reason we respectfully request that the following items be held as confidential.

- Circuit Block Diagrams
- Theory of Operation
- Schematics

The Federal Communications Commission will be notified, in writing of any changes in the software/programming of this device that could affect its RF characteristics.

A table of contents for all submitted materials can be found at the end of this letter.

Please do not hesitate to contact me with any questions you may have regarding this report. As always we look forward to your timely response.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jer P Bos' with a stylized flourish at the end.

Jeremy P. Bos
RF Test Site Manager
Johnson Controls Interiors.
Tel: (616)394-6076/Fax: (616)394-6100
Email: Jeremy.bos@jci.com

Table of Contents

1. General Information.....	2
1.1. Product Description.....	2
1.2. Related Grants.....	2
1.3. Test Methodology.....	2
1.4. Test Facility.....	3
2. Product Labeling.....	3
2.1. Label Drawing and Location on Product.....	3
3. Test Configuration.....	3
4. Block Diagram.....	4
5. Test Setup Photographs.....	4
6. Conducted Emissions Measurements.....	4
7. Radiated Emissions Data.....	4
7.1. Summary of Results.....	4
7.2. Test Equipment Used.....	4
7.3. Test Equipment Setup and Procedure.....	5
7.4. Measured Data.....	5
7.4.1. Measurements of Fundamentals and Harmonics.....	5
7.4.1.1. (Table) DUT Tuned to 288MHz (Fundamental).....	5
7.4.1.2. (Table) DUT Tuned to 310MHz (Fundamental).....	6
7.4.1.3. (Table) DUT Tuned to 418MHz (Fundamental).....	6
7.4.1.4. (Table) 288MHz (Harmonics).....	6
7.4.1.5. (Table) 310MHz (Harmonics).....	7
7.4.1.6. (Table) 418MHz (Harmonics).....	8
7.4.1.7. (Table) 390 MHz Fundamental (in vehicle).....	9
7.4.1.8. (Table) 390 MHz Fundamental (on table).....	9
7.4.1.9. (Table) 390 MHz Harmonics.....	9
7.4.2. Pulsed Operation.....	10
7.4.2.1. (Figure) 30% Duty Cycle.....	10
7.4.2.2. (Figure) 50% Duty Cycle.....	10
7.4.2.3. (Figure) 80% Duty Cycle.....	11
7.4.3. Occupied Bandwidth.....	11
7.4.3.1. (Table) Occupied Bandwidth Measurements.....	11
7.4.3.2. (Figure) Example of Occupied Bandwidth measurement	12
7.4.4. Emission Spectrum.....	12
7.4.4.1. (Figure) 288 MHz.....	13
7.4.4.2. (Figure) 310 MHz.....	13
7.4.4.3. (Figure) 418 MHz.....	14
7.4.4.4. Summary of Emissions Measurements Taken on OATS.....	14
7.4.5. Variation of Supply Voltage.....	15
7.4.5.1. (Figure) Plot of output power over supply voltage.....	15
7.4.5.2. (Table) Output power as a function of supply voltage.....	15
7.4.6. Verification of Non-Operation in Restricted Bands.....	16
7.4.7. Verification of De-activation after 5 seconds.....	16
7.4.8. Tuning Pulse Measurements.....	16
7.4.8.1. (Figure) Coarse Tuning Pulse (288MHz).....	16
7.4.8.2. Fine Tuning Pulse (288MHz).....	17
7.4.8.3. Coarse Tuning Pulse (310MHz).....	17
7.4.8.4. Fine Tuning Pulse (310MHz).....	18
7.4.8.5. Coarse Tuning Pulse (418 MHz).....	18
7.4.8.6. Fine Tuning Pulse (418MHz).....	19
7.4.8.7. Summary of Tuning Pulse Measurements.....	19
7.5. Formulas and Sample Calculations.....	19
7.5.1. Adjustment to account for duty cycle.....	19
7.5.2. Calculation of FCC limits from 15.231.....	20

8. Photos of Product Tested	20
8.1. Front View	
Please refer to attachment named "front_view.jpg"	
8.2. Rear View	
Please refer to attachment named "rear_view.jpg"	
8.3. Unit Disassembled	
Please refer to attachment named "d_assym.jpg"	
8.4. Light Board	
Please refer to attachment named "light_front.jpg"	
Please refer to attachment named "light_back.jpg"	
8.5. Homelink Accessory Board	
Please refer to attachment named "hl3_front.jpg"	
Please refer to attachment named "hl3_back.jpg"	
9. Other Attachments and Description	21
9.1. User Manual	
Please refer to attachment "user_manual.pdf"	
9.2. Schematics/ Tuning Information	
For schematics please refer to attachment "schematics.pdf"	
For tuning information please refer to attachment "tuning.pdf"	
9.3. Theory of Operation	
For schematics please refer to attachment "theory_op.pdf"	