




	<table border="1"> <tr> <td data-bbox="399 1288 766 1400">  </td><td data-bbox="766 1288 1252 1400"> VIA Technologies, Inc. www.viaembedded.com 製造商: 威盛電子股份有限公司 MADE IN TAIWAN </td></tr> <tr> <td data-bbox="399 1400 766 1655"> 品名: 住戶門口機, Door Station Model No 型號: SHP-D01 Input 輸入: 12Vdc $\equiv$, 1 - 1.5A  CC XX xx YY yyy Z z W FCC ID: NCI-VESHDP01A1 Serial No. 序號: </td><td data-bbox="766 1400 1252 1655"> This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful Interference. (2) This device must accept any Interference received, including Interference that may cause. CAUTION!!! To prevent shock, do not remove cover. No user serviceable parts inside. Refer servicing to qualified personnel. 警告使用者 這是甲類產品, 在居住的環境中使用時, 可能會造成射頻干擾, 在這種情況下, 使用者會被要求採取某些適當的對策。 </td></tr> </table>		VIA Technologies, Inc. www.viaembedded.com 製造商: 威盛電子股份有限公司 MADE IN TAIWAN	品名: 住戶門口機, Door Station Model No 型號: SHP-D01 Input 輸入: 12Vdc $\equiv$, 1 - 1.5A  CC XX xx YY yyy Z z W FCC ID: NCI-VESHDP01A1 Serial No. 序號:	This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful Interference. (2) This device must accept any Interference received, including Interference that may cause. CAUTION!!! To prevent shock, do not remove cover. No user serviceable parts inside. Refer servicing to qualified personnel. 警告使用者 這是甲類產品, 在居住的環境中使用時, 可能會造成射頻干擾, 在這種情況下, 使用者會被要求採取某些適當的對策。
	VIA Technologies, Inc. www.viaembedded.com 製造商: 威盛電子股份有限公司 MADE IN TAIWAN				
品名: 住戶門口機, Door Station Model No 型號: SHP-D01 Input 輸入: 12Vdc $\equiv$, 1 - 1.5A  CC XX xx YY yyy Z z W FCC ID: NCI-VESHDP01A1 Serial No. 序號:	This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful Interference. (2) This device must accept any Interference received, including Interference that may cause. CAUTION!!! To prevent shock, do not remove cover. No user serviceable parts inside. Refer servicing to qualified personnel. 警告使用者 這是甲類產品, 在居住的環境中使用時, 可能會造成射頻干擾, 在這種情況下, 使用者會被要求採取某些適當的對策。				