



LTE BAND-4




Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.









Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.



LTE BAND-5



Shenzhen STS Test Services Co., Ltd.



LTE BAND-5



Shenzhen STS Test Services Co., Ltd.




LTE BAND-5



Shenzhen STS Test Services Co., Ltd.



LTE BAND-5



Shenzhen STS Test Services Co., Ltd.




LTE BAND-7



Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.




LTE BAND-7



Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.




LTE BAND-7



Shenzhen STS Test Services Co., Ltd.



LTE BAND-7



Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.



LTE BAND-7



Shenzhen STS Test Services Co., Ltd.




LTE BAND-7




Shenzhen STS Test Services Co., Ltd.



LTE BAND-7







Shenzhen STS Test Services Co., Ltd.



Page 52 of 62


Report No.: STS2007325W08

LTE BAND-41




Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.










Shenzhen STS Test Services Co., Ltd.



LTE BAND-41



Shenzhen STS Test Services Co., Ltd.



Page 62 of 62

Report No.: STS2007325W08

LTE BAND-41



Shenzhen STS Test Services Co., Ltd.