


Internal photo Report No.: R2105A0395

Internal photo



























































































































































































Report No.: R2105A0395 Internal photo



DIV Ant



Main Ant

TA Technology (Shanghai) Co., Ltd.