

GOCOM Technology Co., Ltd.
UNIT 12, 14/F, LIPPO SUN PLAZA, 28 CANTON ROAD TSIM SHA TSUI, KOWLOON, Hong Kong, China

Tel: +8618750555801


Fax: 0085223744662

E-mail: securitygold@sina.com

Date: 2020-4-13

The RF chip, model: BES2000, installed in our product Digital Portable Radio (Model number:GD900, FCC ID: 2ARRE-GD900, IC: 24523-GD900)which supports Bluetooth BDR(GFSK), EDR($\pi/4$ -DQPSK, 8DPSK), BLE functions. And thischip will not support/enable the BLE, BLE function was disabled by the manufacturer inthe software.
Sincerely,

Signature:

A handwritten signature in cursive script that reads "Snow Huang". There is a small asterisk-like mark below the "u" in "Huang".

Snow Huang

Sales Executive