

## American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

July 5, 2004

RE: BenQ Corp.

FCC ID: JVPM100

After a review of the submitted information, I have a few comments on the above referenced Application.

## **Administrative Issues:**

- 1) Please provide a higher resolution sample label. The characters for the FCC ID can not be easily distinguished.
- 2) The operational description contains detailed technical information, but confidentiality is not requested in the confidentiality letter. Please confirm whether confidentiality is desired on this exhibit, and if so, please update the confidentiality letter.
- 3) The block diagram appears to show the device is capable of all 4 modes (850, 900, 1800, 1900 MHz) but the application for FCC appears to only be for 1900. Please confirm which modes the phone is capable for purposes of grant notes. Note that operation in the 850 MHz is normally expected to be for US operation.
- 4) One of the jacks on the bottom appears to be a USB cable connector. If so, is this device intended to be able to be directly connected to a PC. Please confirm and if so, please note that certain labeling and manual information may need to be adjusted for a DoC. Additionally, if this may also be considered a PC peripheral than was the appropriate PC peripheral testing performed (note that this would require a minimum configuration with PC as given in ANSI C63.4)?
- 5) The operational description does not mention the GPRS class. Please confirm the GPRS class of this device.
- FYI....In the future, please upload SAR or MPE information as RF exposure information instead of Test Reports.

## **Technical Issues:**

- General Conducted spurious emissions as previously discussed do not appear to have been provided.
- 8) Please add the worse case plot for Right Cheek testing (not tilted) and keypad up to the SAR report.

Timothy R. Johnson Examining Engineer

mailto: tjohnson@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

• Page 2 July 5, 2004

Any questions about the content of this correspondence should be directed to the sender.