

See Manual Before Use Voir Manuel Avant Usage

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, 2) This device must accept any interference received, including interference that may cause undesired operation.



LISTED

E145532



ATTENTION
OBSERVE PRECAUTIONS
FOR HANDLING
ELECTROSTATIC
SENSITIVE DEVICES



E134

<http://cisco-returns.com>

-40°C to 57°C

LISTED AS I.T.E. FOR USE IN HAZARDOUS
LOCATIONS

Class I, Div 2, Groups A B C D

Class I, Zone 2, Ex na IIC T4 Gc

CE II 3 G, Ex na IIC T4 Gc

DEMKO 14 ATEX 1358X

Class I, Zone 2, AEx na IIC T4 Gc

Country of Origin Mexico

Cisco Systems, Inc.

170 W. Tasman Dr, San Jose, CA USA

MODEL: IR509UWP-915

FCC ID: LDK-IR509UWP

IC: 2461B-IR509UWP



PID VID: IR509UWP-915/K9 V01



TAN: 68-5082-01 A0



SN: JMX1837X000