Client: Alinco, Inc Model: DJ-S40T Standards: FCC 15.121/IC RSS-215 Report #: 2003079 Date: May 21, 2003

APPENDIX A: CHANGED EUT COMPONENTS

Please refer to the following page for a list of the changed components in the EUT; the reason for this Type II permissive change report and application.

Below is the list of the changes applied to the new version of DJ-S40T compare to the current version:

 $\label{eq:component} \begin{array}{ll} \mbox{Old} > New \\ (1) \mbox{Power amplifier Q3: MRF9745} > 2SK3074 \\ (2) \mbox{Pre-driver IC1: $$\mu$PC2771T} > μPC2771TB \\ (3) \mbox{3Vdc regulator IC10: $$S-816A30AMC} > XC6202P302PR \\ (4) \mbox{CPU IC7: $$M38224M6H155HP(XA0853) > $M38224M6M233HP$ (XA0903) \\ (5) \mbox{Printed circuit board UP0433} > UP0446B \\ \end{array}$

The above changes are mentioned on the following documents: Parts list: All (1) to (5) Block diagram: (1),(2),(3) Schematic diagram: (1),(2),(3) 800MHz cellurar block letter: (4)

== End of document