




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB24@0 8.571MHz




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB24@0 8.570MHz




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB24@0 8.612MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.459MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 13.458MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB36@0 13.463MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB36@0 13.461MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB36@0 13.463MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB38@0 13.570MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB38@0 13.577MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB38@0 13.574MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB38@0 13.524MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.024MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 18.092MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB50@0 18.100MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB50@0 18.017MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB50@0 18.010MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB51@0 18.106MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB51@0 18.173MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB51@0 18.169MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB51@0 18.182MHz



n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.616MHz



n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 27.633MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB75@0 27.737MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM RB75@0 27.510MHz



n77_2_30MHz_30kHz_3625MHz_CP-OFDM 16
QAM RB78@0 27.765MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM 256
QAM RB78@0 27.758MHz




n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.461MHz




n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 37.471MHz



n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB100@0 37.199MHz



n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB100@0 37.180MHz



n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB100@0 37.285MHz



n77_2_40MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB106@0 37.787MHz

