



Testing Tomorrow's Technology

January 19, 2015

ACB
Applications Examiner

**RE: FCC PART 15 and IC PERMISSIVE CHANGE for RFM,
FCC ID: HSW-DNT24, IC: 4492A-DNT24**

Dear Application Examiner:

RFM has replaced an obsolete power amplifier, PA2423L made by Skyworks, with a new power amplifier, SE2433T made by Skyworks, on the previously approved radio module referenced above. This is the reason for this permissive change request. The radio module itself has not changed. This version incorporates the following change: The obsolete power amplifier, PA2423L had been replaced by a new power amplifier SE2433T.

A schematic with the details of the new power amplifier is attached and the radio module has been retested for compliance. Please review all the supporting documentation including the test report for this class 2 permissive change request.

Additionally a KDB inquiry was submitted and approved. The inquiry number is as follows:
231311

Best Regards,

A handwritten signature in cursive script, appearing to read 'Sandi McEnergy', written in black ink.

Sandi McEnergy
Agent for RFM

**3505 Francis Circle, Alpharetta, GA 30004
PH: 770-740-0717 Fax: 770-740-1508
www.ustech-lab.com**