




Test accessories




Activator cable



USB cable for monitor




Setup for measurements below 1 GHz



Setup for measurements below 1 GHz



EUT test setup below 1 GHz




Setup for measurements above 1 GHz




Setup for measurements above 1 GHz



EUT test setup above 1 GHz



Setup for measurements above 1 GHz



Setup for measurements above 1 GHz

