







ac40 5.230 GHz



ac80 5.210 GHz




Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03









Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03











Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03










Antenna 4:




a20 5.240 GHz








Report No.: AAEMT/RF/231110-04-03

n20 5.240 GHz





n40 5.190 GHz







Report No.: AAEMT/RF/231110-04-03







ac40 5.190 GHz



Report No.: AAEMT/RF/231110-04-03





ac80 5.210 GHz






Report No.: AAEMT/RF/231110-04-03


ax20 5.240 GHz





Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03









Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03

