

Date 01 Sept 2022

Federal Communications Commission Equipment Authorization Branch 7435 Oakland Mills Road Columbia, MD 21046 United States of America

Subject: FCC Labelling Requirements; Compliance Statement on TSL Reader Products.

To Whom it May Concern.

Due to the lack of available space on the TSL range of readers, ICT is unable to label the reader devices with the following FCC Compliance Statement:

"This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

Integrated Control Technology has labelled each TSL Reader with the FCC ID Number associated with the device and the FCC logo and QR code which directs the purchaser to the product manual for the device. As required by FCC part 15 requirements.

Within the product manual the full text of the FCC part 15 compliance statement is displayed for compliance purposes.

Yours sincerely

Hayden Burr.

Chief Executive Officer

Integrated Control Technology



FCC ID: I CAN ICE EN 5013 EN 5013	lodel: RA-RK-HL UAUSLX S-3 (A)/NMB-3(1-1:2006 1-3:2009 9-11-1:2013		FC R-I	5D.	16 12 14 15 15 15 15 15 15 15
	(U)	LISTED SECURITY EQUIPMENT 4R		EQUIPMEN 4RN1 ACC CONTROL UNIT REAL	octive Harm.
			LISTE	D	କୁ ଜୁକୁ ଅକ୍ଷୟ www.P65Warnings.ca.gov
					IING: Cancer 965Warnings
					WARN
For Productinformation	1			Red	+12V
	815 612 113	2022	2-W36	Black Green White Brown Blue Yellow Purple	OV DATA 0 DATA 1 LED BLUE BEEPER NA