



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 7, 2006

RE: Mobile Access Networks

FCC ID: OJFMA850A

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Each application must stand on its own and therefore the Photographs of the TX board and Card (both TX) must be provided showing underneath the shields. Please provide.
- 2) The manual reference to LDK-102042 appears to need to be LDK102042. Please review/correct.
- 3) Previous comment 3) is not complete. By reference to RF conducted tests, this also includes such items as 6 dB bandwidth, RF power, PSD, etc, for the test configuration consisting of 802.11b/g + 802.11a + Part 22/24. If these have been verified to not have changed for the additional of Part 22/24, please explain. Otherwise please provide appropriate data.
- 4) FYI... Please note that labels must be placed on the access points themselves and the previous FCC ID's on them should be covered or removed.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.