

ATTEN 30dB

RL 23.5dBm

10dB/

MKR -34.67dBm

3.78GHz


FCC ID: NM8FALCON

PCS Ch.600

DISPLAY LINE
-13.0 dBm

D

R



START 2.50GHz

STOP 20.00GHz

RBW 1.0MHz

VBW 1.0MHz

SWP 350ms

FCC ID: NM8FALCON

ATTEN 30dB

RL 23.5dBm

10dB/

MKR -28.33dBm

1.8940GHz


FCC ID: NM8FALCON

FCS Ch. 1175

DISPLAY LINE
-13.0 dBm

D

μ



START 10MHz

STOP 2.500GHz

RBW 1.0MHz

VBW 1.0MHz

SWP 50.0ms

FCC ID: NM8FALCON

ATTEN 30dB

RL 23.5dBm

10dB/

MKR -33.50dBm

3.84GHz


FCC ID: NM8FALCON

PCS Ch. 1175

DISPLAY LINE
-13.0 dBm

D

R



START 2.50GHz

STOP 20.00GHz


RBW 1.0MHz

VBW 1.0MHz


SWP 350ms

FCC ID: NM8FALCON


✱ Agilent 22:14:44 Nov 20, 2002




* Agilent 22:19:56 Nov 20, 2002




* Agilent 22:21:47 Nov 20, 2002




Agilent 22:27:28 Nov 20, 2002




Agilent 22:28:46 Nov 20, 2002




Agilent 22:33:28 Nov 20, 2002




Agilent 22:35:28 Nov 20, 2002




Agilent 22:37:26 Nov 20, 2002




Agilent 22:38:46 Nov 20, 2002




※ Agilent 22:40:40 Nov 20, 2002




※ Agilent 22:42:01 Nov 20, 2002





✱ Agilent 22:42:59 Nov 20, 2002





✱ Agilent 22:43:59 Nov 20, 2002







FCC ID: NM8FALCON

Digital EMC Co., Ltd.





FCC ID: NM8FALCON

Digital EMC Co., Ltd.



FCC ID: NM8FALCON

Digital EMC Co., Ltd.



FCC ID: NM8FALCON