

Exhibit J

Section 2: WRT-2100 Tune-Up Information

WRT-2100

Exhibit J – Section 2: Tune-Up Information

Section 2 contains the Production Test Requirement documents. Listed below are the Rockwell Collins Parts Number , Item Description and Page information.

Rockwell Collins Parts List Part Number	Item Description	Page
829-7072-050	PRODUCTION TEST REQUIREMENTS FOR THE WRT-701, WRT-2100 POWER SUPPLY	J-98
983-4167-050	PRODUCTION TEST REQUIREMENTS FOR WINDSHEAR WEATHER RADAR WRT-2100 (CPN 822-1710-9(ALL STATUSES))	J-106
983-4179-050	PRODUCTION TEST REQUIREMENTS FOR THE WRT-2100 SOURCE BOARD CPN 827-4833-05(ALL STATUSES)	J-223
983-4949-001	PRODUCTION TEST REQUIREMENTS FOR WRT-701X AND WRT-2100 A53 BITE AND RF SUPPLY CPN 828-1495-001	J-241
829-7079-001	PRODUCTION TEST REQUIREMENTS FOR THE WRT-701X WINDSHEAR AND PACER CRAG 2ND IF ASSEMBLY (CPN 827-3308-XXX & 830-5908-XXX)	J-256