







Report No.: AAEMT/RF/231110-04-03








Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03

ax80 5.775 GHz





Report No.: AAEMT/RF/231110-04-03

Antenna 2:





Report No.: AAEMT/RF/231110-04-03


a20 5.240 GHz





Report No.: AAEMT/RF/231110-04-03





n20 5.240 GHz





n40 5.190 GHz




n40 5.230 GHz





ac20 5.180 GHz



ac20 5.240 GHz









Report No.: AAEMT/RF/231110-04-03

ac80 5.210 GHz



Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03



Report No.: AAEMT/RF/231110-04-03






Report No.: AAEMT/RF/231110-04-03




Report No.: AAEMT/RF/231110-04-03










Report No.: AAEMT/RF/231110-04-03







Report No.: AAEMT/RF/231110-04-03





Report No.: AAEMT/RF/231110-04-03







Antenna 3:




a20 5.240 GHz











Report No.: AAEMT/RF/231110-04-03



