

Hyundai Corporation
25, Yulgok-ro 2-Gil, Jongno-gu, Seoul, South Korea

2016-9-6

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

List of Differences for FCC ID: RQQHLT-E50FSL

Location	Old PCB of FCC ID: RQQHLT-E50FSL, Model: E500	New PCB of FCC ID: RQQHLT-E50FSL, Model: e501
Camera	Front Camera: 0.3MP FF; Back Camera: 5.0MP FF	Front Camera: 0.3MP FF; Back Camera: 2.0MP FF
Fingerprint lock	With Finger print Sensor	Without Finger print Sensor

Sincerely,

Hyundai Corporation

Hans Hanbich Kim, Overseas Sales Manager

