	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHA111LW		Page 1(4)
Author Data Daoud Attayi	Dates of Test July 14-15, 2014	Report No RTS-6058-1407-07	FCC ID L6ARHA110LW

Annex E: Test set up photos



	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHA111LW		Page 2(4)
Author Data Daoud Attayi	Dates of Test July 14-15, 2014	Report No RTS-6058-1407-07	FCC ID L6ARHA110LW



Figure E1. BlackBerry Smartphone

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHA111LW		Page 3(4)
Author Data Daoud Attayi	Dates of Test July 14-15, 2014	Report No RTS-6058-1407-07	FCC ID L6ARHA110LW






Figure E2: Ambient noise and system validation measurement setup

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHA111LW		Page 4(4)
Author Data Daoud Attayi	Dates of Test July 14-15, 2014	Report No RTS-6058-1407-07	FCC ID L6ARHA110LW




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup