



15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:52:35

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:53:25

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -45.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:56:59

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:58:27

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -46.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:18:15

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB100@0 -46.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:19:04

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB1@105 -37.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:21:27

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB100@0 -46.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:22:19

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -46.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:00:17

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0 -46.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:01:34

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB1@50 -46.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:03:41

20MHz_30kHz_3970MHz_DFT-s-OFDM QPSK_RB50@0 -46.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:04:49

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -43.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:24:20

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -46.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:25:09

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB1@159 -40.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:27:41

30MHz_15kHz_3965MHz_DFT-s-OFDM QPSK_RB160@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:28:30

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:30:15

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -46.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:31:04

40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB1@215 -27.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:33:26

40MHz_15kHz_3960MHz_DFT-s-OFDM QPSK_RB216@0 -46.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:34:42

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:05:56

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -46.68 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:06:59

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB1@105 -44.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:16:47

40MHz_30kHz_3960MHz_DFT-s-OFDM QPSK_RB100@0 -46.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:45:14

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -42.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:36:13

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -46.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:37:02

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB1@269 -38.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:42:31

50MHz_15kHz_3955MHz_DFT-s-OFDM QPSK_RB270@0 -46.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 09:43:45

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:46:23

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -46.73 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 10:53:11


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB1@132 -46.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 10:56:51


50MHz_30kHz_3955MHz_DFT-s-OFDM QPSK_RB128@0 -46.36 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 10:58:08


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -46.55 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 10:59:18


60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.61 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:06:15


60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB1@161 -42.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:09:54


60MHz_30kHz_3950MHz_DFT-s-OFDM QPSK_RB162@0 -46.31 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 26.MAY.2024 11:12:10

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -43.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:13:38

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -46.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:15:05

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB1@188 -45.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:17:34

70MHz_30kHz_3945MHz_DFT-s-OFDM QPSK_RB180@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:18:27

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -20.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:21:08

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -41.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:21:59

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB1@216 -19.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:25:47

80MHz_30kHz_3940MHz_DFT-s-OFDM QPSK_RB216@0 -46.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:26:40

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -19.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:28:15

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -40.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:29:07

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB1@244 -17.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:32:31

90MHz_30kHz_3935MHz_DFT-s-OFDM QPSK_RB243@0 -46.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:33:23


100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -20.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:34:34


100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -41.28 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:35:52


100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB1@272 -17.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:38:54

100MHz_30kHz_3930MHz_DFT-s-OFDM QPSK_RB270@0 -46.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:40:15

n78_1


10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0 -43.54 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:09:37


10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0 -43.49 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:11:20


10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23 -43.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:12:28


10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0 -43.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:14:23


15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0 -42.85 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:16:16


15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0 -43.53 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:17:48


15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37 -41.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:19:22


15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0 -43.83 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:21:33


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@0 -43.26 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:23:36


25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB64@0 -43.66 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:25:01


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@64 -43.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:27:36


25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB64@0 -43.81 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:29:31


30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0 -42.06 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:31:06


30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0 -43.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:35:03


30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77 -38.02 dBm




30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0 -43.75 dBm




40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -39.54 dBm




40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -42.66 dBm




40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -34.25 dBm



40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -43.73 dBm




50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -37.22 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:50:16


50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -43.61 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 14:51:50


50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -33.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:00:08


50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -43.68 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:02:10


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -29.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:05:49


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -43.36 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:07:58


60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161 -29.59 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:09:33


60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0 -43.17 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:29:31


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -36.40 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:40:10


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -43.67 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:42:25


70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -30.17 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:43:36


70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -43.67 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:46:04


80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0 -26.85 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:47:30


80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0 -26.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:49:11


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -27.95 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:51:07


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -35.90 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:52:37


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -26.29 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:54:07


90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -26.17 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:55:29


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -25.56 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 15:58:06


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -40.58 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 16:00:08


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -23.34 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 16:01:46

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -29.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 25.MAY.2024 16:27:24

n78_3


10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:41:38


10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -46.72 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:44:05


10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB1@51 -29.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:50:57


10MHz_15kHz_3795MHz_DFT-s-OFDM QPSK_RB50@0 -47.15 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 11:52:12


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.60 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 13:19:17


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -46.52 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 13:20:44


10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@23 -42.73 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 26.MAY.2024 13:28:11


10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB24@0 -47.13 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 26.MAY.2024 13:29:12

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -45.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:53:57

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 11:55:48

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -31.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:04:31

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:06:10

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:30:56

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:32:22

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -45.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:34:46

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:37:09

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -45.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:08:59

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -46.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:10:37

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -39.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:17:31

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -47.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:18:44

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:38:36

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -46.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:39:40

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -45.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:43:11

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -47.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:44:36

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -43.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:20:06

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -46.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:21:11

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -37.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:25:33

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:26:29

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -46.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:46:02

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -46.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:47:20

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:50:39

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -47.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:51:32

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:28:40

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -46.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:32:39

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@215 -23.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:12:38

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB216@0 -45.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 12:52:20

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.04 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:53:08

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -46.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:54:20

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -42.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:40:06

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:03:51

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -32.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:13:59

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -46.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:15:02

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -33.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:16:44

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -47.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 13:18:10

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:41:23

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -46.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:05:59

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:08:50

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:09:55

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -43.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:12:00

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:13:40

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -45.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:15:21

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:16:51

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -46.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:18:05

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -46.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:18:58

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -45.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:20:51

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:21:50

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -21.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:23:12

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -42.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:25:07

80MHz_30kHz_3760MHz_DFT-s-OFDM QPSK_RB1@216 -21.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:27:14

80MHz_30kHz_3760MHz_DFT-s-OFDM QPSK_RB216@0 -47.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:28:30

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0 -20.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:29:43

90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB243@0 -40.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:30:46

90MHz_30kHz_3755MHz_DFT-s-OFDM QPSK_RB1@244 -17.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:32:21

90MHz_30kHz_3755MHz_DFT-s-OFDM QPSK_RB243@0 -47.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:33:15

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -18.00 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:44:00

100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -40.38 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 26.MAY.2024 14:36:29