

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISSED RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202

INTERNAL PHOTOGRAPHS




Figure 1. RAC00-17202 with Cover Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISSED RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202



Figure 2. RAC00-17202 with Electronic Module lifted

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISSED RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202




Figure 3. Electronic Module removed (Rear)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISSED RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202




Figure 4. Electronic Module (Front)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISD RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202




Figure 5. RAC00-17202 – Main PCB (Front Side)




Figure 6. RAC00-17202 – Main PCB (Back Side)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15, 95, ISSED RSS 210
KE3-3003679
2721A-300-3679
20-0276
October 30, 2020
Radio Systems
RAC00-17202




Figure 7. RAC00-17202 – Electronic Module PCB (Front side)




Figure 8. Electronic Module PCB (Back side)