Fanvil Technology Co., LTD.

Address: 10/F Block A, Dualshine Global Science Innovation HonglangNorth 2nd Road,

Bao'an District, Shenzhen, 518101, China

Tel: 86-0755-26402199 Fax: 86-0755-26402618

Email: mengiiao.Hu@fanvil.com

The RF chip, model: **RTL8761BTV**, installed in our product IP Phone, model: X5U V2,FCC ID: 2APPZ-X5UV2, this chip supports EDR( $\pi$ /4-DQPSK,8DPSK), BDR(GFSK) and BLE1M/2M function, but for marketing purpose, this chip only supports EDR( $\pi$ /4-DQPSK,8DPSK), BDR(GFSK) and BLE1M. The BLE 2M was disabled to use by manufacture in the software, the end user has no capability to activate it.

Sincerely,
Signature: Mengjiao Hu

Certified Engineer