



June 3, 2004

Subject: FCC ID: RAXWN4501DARC

Dear Sir,

The Siemens Gigaset USB Adapter 54, Model No.: S30853-S1016-R107, FCC ID: RAXWN4501DARC need to change the FCC ID: RSE-ST120G and Model No.: SpeedTouch 120g. We evaluated that the changed would NOT affect the RF characteristics except for the Radiated Spurious Emission & Band edge.

If you have any question, please feel free to contact me.

Best Regards,

A handwritten signature in black ink that reads "Victor Wen". The signature is written in a cursive, flowing style.

**Victor Wen**

**Supervisor**

**Intertek Testing Service Taiwan Ltd.**