



Intertek Report No.: 231204042SZN-005_Appendix C



Band2-5MHz-QPSK-19175-25RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Statistic Count 20 7 20 Out of Tolerance 0.00 % Detected Modulation 16-QAM Detected Channel Type PUSCH View Filter Throughput 100.0 % Display


Band2-5MHz-16QAM-18900-25RB#0




Band2-5MHz-16QAM-19175-25RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band2-10MHz-QPSK-18900-50RB#0




Band2-10MHz-QPSK-19150-50RB#0




Intertek Report No.: 231204042SZN-005_Appendix C







Band2-10MHz-16QAM-18900-50RB#0




Band2-10MHz-16QAM-19150-50RB#0








Band2-15MHz-QPSK-18900-75RB#0




Band2-15MHz-QPSK-19125-75RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band2-15MHz-16QAM-18675-75RB#0





Band2-15MHz-16QAM-18900-75RB#0





Band2-15MHz-16QAM-19125-75RB#0













Band2-20MHz-QPSK-19100-100RB#0




Intertek Report No.: 231204042SZN-005_Appendix C







Band2-20MHz-16QAM-18900-100RB#0




Band2-20MHz-16QAM-19100-100RB#0








Band4-1.4MHz-QPSK-20175-6RB#0




Band4-1.4MHz-QPSK-20393-6RB#0






Band4-1.4MHz-16QAM-19957-6RB#0



Band4-1.4MHz-16QAM-20175-6RB#0



Band4-1.4MHz-16QAM-20393-6RB#0