

Report No.: SEWM2210000205RG02

Rev.: 01

Page: 198 of 199

Frequency Stability for SA

Test Result

Frequency Error VS. Voltage

Voltage										
Band	SCS	Bandwidth	Modulation	Channel	RB Config	Voltage	Temperature	Deviation(Hz)	Deviation (ppm)	Verdict
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	VH	NT	9.700000	0.002771	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	VN	NT	8.700000	0.002486	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	VL	NT	8.100000	0.002314	PASS
N77-3450-3550	30	100	CP-QPSK	M	Outer_Full	VH	NT	17.000000	0.004857	PASS
N77-3450-3550	30	100	CP-QPSK	M	Outer_Full	VN	NT	10.500000	0.003000	PASS
N77-3450-3550	30	100	CP-QPSK	M	Outer_Full	VL	NT	9.800000	0.002800	PASS



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

South of No. 6 Plant, No. 1, Runsheng Road, Suzhou Industrial Park, Suzhou Area, China (Jiangsu) Pilot Free Trade Zone 215000
中国·苏州·中国(江苏)自由贸易试验区苏州片区苏州工业园区润胜路1号的6号厂房南面 邮编: 215000

t (86-512) 62992980 www.sgs.com.cn
t (86-512) 62992980 sgs.china@sgs.com

Report No.: SEWM2210000205RG02

Rev.: 01

Page: 199 of 199

Frequency Error VS. Temperature

Voltage										
Band	SCS	Bandwidth	Modulation	Channel	RB Config	Voltage	Temperature	Deviation(Hz)	Deviation (ppm)	Verdict
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	-30	8.600000	0.002457	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	-20	10.900000	0.003114	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	-10	6.400000	0.001829	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	0	7.600000	0.002171	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	10	4.300000	0.001229	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	20	13.500000	0.003857	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	30	12.800000	0.003657	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	40	3.400000	0.000971	PASS
N77-3450-3550	30	100	DFT-QPSK	M	Outer_Full	NV	50	9.100000	0.002600	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	-30	7.400000	0.002114	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	-20	4.100000	0.001171	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	-10	7.300000	0.002086	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	0	2.200000	0.000629	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	10	8.300000	0.002371	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	20	4.700000	0.001343	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	30	3.400000	0.000971	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	40	6.500000	0.001857	PASS
N78-3450-3550	30	100	CP-QPSK	M	Outer_Full	NV	50	6.700000	0.001914	PASS

---End of Attachment---



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
 South of No. 6 Plant, No. 1, Runsheng Road, Suzhou Industrial Park, Suzhou Area, China (Jiangsu) Pilot Free Trade Zone 215000 t (86-512) 62992980 www.sgsgroup.com.cn
 中国·苏州·中国(江苏)自由贸易试验区苏州片区苏州工业园区润胜路1号的6号厂房南楼 邮编: 215000 t (86-512) 62992980 sgs.china@sgs.com