


RUBICOM SYSTEMS, INC.



**FCC TEST REPORT
(INTENTIONAL RADIATOR)
FOR THE
ROCKWELL COLLINS, INC.
VHF-4000 COMMUNICATIONS TRANSCEIVER
(118-137MHz)**



Rubicom Systems, Inc.
284 West Drive, Suite B
Melbourne, FL 32904

THIS REPORT SHALL NOT BE REPRODUCED
EXCEPT IN FULL WITHOUT THE WRITTEN
APPROVAL OF THE TESTING LABORATORY

FCC TEST REPORT
(INTENTIONAL RADIATOR)
FOR THE
ROCKWELL COLLINS, INC.
VHF-4000 COMMUNICATIONS TRANSCEIVER
(118-137MHz)
S/N: FBLF

PART 3

Prepared by: _____
Joseph G. Barbee

Tested by: _____
Alex Belardinelli

Performed by:
RUBICOM SYSTEMS, INC.
284 West Drive, Suite B
Melbourne, Florida 32904

Performed for:
ROCKWELL COLLINS, INC.
1100 W. Hibiscus Blvd.
Melbourne, Florida 32901

Received: September 9, 2001


Completed: September 12, 2001

TEST: RADIATED EMISSIONS	EUT: VHF-4000	S/N: FBLF
FREQ: 1-2GHZ	SPEC: FCC PART 15	ANT: HT/POL: H
DETECTOR: AVERAGE	LINE UNDER TEST: N/A	EUT POSITION:
DATE: 9/11/01	TEST SITE: 3-METER	TESTER: AB

REF 97.0 dB μ V/m
10dB/

ATT 0 dB

A_write B_blank




DL 54.0 dB μ V/m

RBW 1 MHz
VBW 10 Hz
SWP 200 s

START 1.000 GHz

STOP 2.000 GHz





DATA SHEET 6.1-8

