



Band 17_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 11:23:13

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 11:23:34

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 11:23:52

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 11:24:13

Band 17_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 11:24:37

Band 17_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 11:24:54

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 11:25:24

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 11:25:46

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 12.MAR.2022 11:26:18

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 12.MAR.2022 11:26:40

Band 17_10 MHz_High_QPSK_RB50#0




Date: 12.MAR.2022 11:27:08

Band 17_10 MHz_High_16QAM_RB50#0




Date: 12.MAR.2022 11:27:27

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 14:42:51

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 14:43:05

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 14:43:27

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 14:43:44

Band 38_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 14:44:03

Band 38_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 14:44:23


Band 38_10 MHz_Low_QPSK_RB50#0



Band 38_10 MHz_Low_16QAM_RB50#0




Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 12.MAR.2022 14:45:28

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 12.MAR.2022 14:45:50

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 14:47:00

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 14:47:24

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 12.MAR.2022 14:47:48

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 12.MAR.2022 14:48:15

Band 38_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 14:48:37

Band 38_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 14:49:04

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 14:49:27

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 14:50:00

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 12.MAR.2022 14:50:27

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 12.MAR.2022 14:50:58

Band 38_20 MHz_High_QPSK_RB100#0




Date: 12.MAR.2022 14:51:22

Band 38_20 MHz_High_16QAM_RB100#0




Date: 12.MAR.2022 14:51:49

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 15:38:25

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 15:38:39

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 15:38:55

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 15:39:12

Band 41_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 15:39:30

Band 41_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 15:39:48

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 15:40:11

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 15:40:33

Band 41 10 MHz Middle QPSK RB50#0




Date: 12.MAR.2022 15:40:55

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 12.MAR.2022 15:41:17

Band 41_10 MHz_High_QPSK_RB50#0



Date: 12.MAR.2022 15:41:33

Band 41_10 MHz_High_16QAM_RB50#0



Date: 12.MAR.2022 15:41:54