





11A-CDD_Ant1_7095





Date: 21.SEP.2022 19:13:08

11A-CDD_Ant2_7095




Date: 21.SEP.2022 19:14:11









11AX20MIMO_Ant1_5955




11AX20MIMO_Ant2_5955








11AX20MIMO_Ant1_6415




11AX20MIMO_Ant2_6415






11AX20MIMO_Ant1_6435



Date: 21.SEP.2022 19:27:32


11AX20MIMO_Ant2_6435



Date: 21.SEP.2022 19:28:36



11AX20MIMO_Ant1_6475




11AX20MIMO_Ant2_6475





11AX20MIMO_Ant1_6515




11AX20MIMO_Ant2_6515






11AX20MIMO_Ant1_6535




11AX20MIMO_Ant2_6535






11AX20MIMO_Ant1_6695




11AX20MIMO_Ant2_6695






11AX20MIMO_Ant1_6855




11AX20MIMO_Ant2_6855





11AX20MIMO_Ant1_6875




11AX20MIMO_Ant2_6875






11AX20MIMO_Ant1_6895




11AX20MIMO_Ant2_6895






11AX20MIMO_Ant1_6995




11AX20MIMO_Ant2_6995






11AX20MIMO_Ant1_7095




11AX20MIMO_Ant2_7095








11AX20MIMO_Ant1_7115



11AX20MIMO_Ant2_7115











11AX40MIMO_Ant1_6405



Date: 21.SEP.2022 20:07:14


11AX40MIMO_Ant2_6405




Date: 21.SEP.2022 20:08:13



11AX40MIMO_Ant1_6445




11AX40MIMO_Ant2_6445






11AX40MIMO_Ant1_6485




11AX40MIMO_Ant2_6485






11AX40MIMO_Ant1_6525



Date: 21.SEP.2022 20:15:44


11AX40MIMO_Ant2_6525




Date: 21.SEP.2022 20:16:46



11AX40MIMO_Ant1_6565




11AX40MIMO_Ant2_6565





11AX40MIMO_Ant1_6685



11AX40MIMO_Ant2_6685

