



Band 25_3 MHz_Low_QPSK




Date: 4.NOV.2022 09:53:06

Band 25_3 MHz_Low_16QAM




Date: 4.NOV.2022 09:53:30

Band 25_3 MHz_High_QPSK




Date: 4.NOV.2022 09:54:18

Band 25_3 MHz_High_16QAM




Date: 4.NOV.2022 09:54:42

Band 25_5 MHz_Low_QPSK




Date: 4.NOV.2022 09:56:54

Band 25_5 MHz_Low_16QAM




Date: 4.NOV.2022 09:57:19

Band 25_5 MHz_High_QPSK




Date: 4.NOV.2022 09:58:45

Band 25_5 MHz_High_16QAM




Date: 4.NOV.2022 09:59:10

Band 25_10 MHz_Low_QPSK




Date: 4.NOV.2022 10:01:19

Band 25_10 MHz_Low_16QAM




Date: 4.NOV.2022 10:01:43

Band 25_10 MHz_High_QPSK




Date: 4.NOV.2022 13:05:46

Band 25_10 MHz_High_16QAM




Date: 4.NOV.2022 13:07:30

Band 25_15 MHz_Low_QPSK




Date: 4.NOV.2022 10:10:07

Band 25_15 MHz_Low_16QAM




Date: 4.NOV.2022 10:10:31

Band 25_15 MHz_High_QPSK




Date: 4.NOV.2022 10:11:12

Band 25_15 MHz_High_16QAM




Date: 4.NOV.2022 10:11:37

Band 25_20 MHz_Low_QPSK




Date: 4.NOV.2022 10:13:39

Band 25_20 MHz_Low_16QAM




Date: 4.NOV.2022 10:14:04

Band 25_20 MHz_High_QPSK




Date: 4.NOV.2022 10:14:52

Band 25_20 MHz_High_16QAM




Date: 4.NOV.2022 10:17:42

Part 22H_Band 26_1.4 MHz_Low_QPSK




Date: 4.NOV.2022 14:27:06

Part 22H_Band 26_1.4 MHz_Low_16QAM




Date: 4.NOV.2022 14:27:31

Part 22H_Band 26_1.4 MHz_High_QPSK




Date: 4.NOV.2022 14:30:00

Part 22H_Band 26_1.4 MHz_High_16QAM




Date: 4.NOV.2022 14:30:24

Part 22H_Band 26_3 MHz_Low_QPSK




Date: 4.NOV.2022 14:34:16

Part 22H_Band 26_3 MHz_Low_16QAM




Date: 4.NOV.2022 14:34:41

Part 22H_Band 26_3 MHz_High_QPSK




Date: 4.NOV.2022 14:35:29

Part 22H_Band 26_3 MHz_High_16QAM




Date: 4.NOV.2022 14:35:53

Part 22H_Band 26_5 MHz_Low_QPSK




Date: 4.NOV.2022 14:36:43

Part 22H_Band 26_5 MHz_Low_16QAM




Date: 4.NOV.2022 14:37:08

Part 22H_Band 26_5 MHz_High_QPSK




Date: 4.NOV.2022 14:37:56

Part 22H_Band 26_5 MHz_High_16QAM




Date: 4.NOV.2022 14:38:20

Part 22H_Band 26_10 MHz_Low_QPSK




Date: 4.NOV.2022 14:40:42

Part 22H_Band 26_10 MHz_Low_16QAM




Date: 4.NOV.2022 14:41:07

Part 22H_Band 26_10 MHz_High_QPSK




Date: 4.NOV.2022 14:55:29

Part 22H_Band 26_10 MHz_High_16QAM




Date: 4.NOV.2022 14:43:38

Part 22H_Band 26_15 MHz_Low_QPSK




Date: 4.NOV.2022 14:47:21

Part 22H_Band 26_15 MHz_Low_16QAM




Date: 4.NOV.2022 14:49:37

Part 22H_Band 26_15 MHz_High_QPSK




Date: 4.NOV.2022 14:50:50

Part 22H_Band 26_15 MHz_High_16QAM




Date: 4.NOV.2022 14:51:15

Part 90_Band 26_1.4 MHz_Low_QPSK




Date: 4.NOV.2022 16:40:09

Part 90_Band 26_1.4 MHz_Low_16QAM




Date: 4.NOV.2022 16:39:32

Part 90_Band 26_1.4 MHz_High_QPSK




Date: 4.NOV.2022 16:37:07

Part 90_Band 26_1.4 MHz_High_16QAM




Date: 4.NOV.2022 16:37:57

Part 90_Band 26_3 MHz_Low_QPSK



Date: 4.NOV.2022 16:32:29

Part 90_Band 26_3 MHz_Low_16QAM



Date: 4.NOV.2022 16:33:05