



Appendix C – SAR Test Setup Photos



Test Position Side A 10 mm Gap





Test Position Side B 10 mm Gap





Test Position Side C 10 mm Gap





Test Position Side D 10 mm Gap






Test Position Side E 10 mm Gap





Test Position Side F 10 mm Gap





Test Locations





Front of Device





Back of Device